

Additional Funding Request

DE002	CSS# 22800 WO# 11431 Asset# BOILER assets 1705 and 1706			
Description of Repairs	Labor and materials needed to clean out the scale in both boilers.			
Diagnosis: Initial Work Order	As per the annual boiler certification, there is a moderate amount of scale in the boilers that needs to be cleaned out in both of the boilers. Assets 1705 and 1706			
Diagnostic Fee	\$ 0.00			
Additional Labor Cost to Perform Repairs	\$ 1000 Labor \$100/hr x 10			
Additional Cost	\$ 			
Total Cost of Repair	\$ 1,000.00			



S&S MECHANICAL

S&S Mechanical
4845 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 176

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 11431
Quote No: 176
Site: DE002 Savannah Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 01/31/2020
Valid For: 30 Day(s)

WO#: 11431

CSS Ticket Number: 22800

Problem: As per the annual boiler certification, there is a moderate amount of scale in the boilers that needs to be cleaned out in both of the boilers

S&S will need more labor to complete this work order.

Service

Item	Quantity	Unit Price	Total
HVAC Labor Rate	10	\$100.00	\$1,000.00
Sub-Total ex Tax			\$1,000.00
Tax			\$0.00
Total inc Tax			\$1,000.00

Labor	\$1,000.00
Sub-Total ex Tax	\$1,000.00
Tax	\$0.00
Total inc Tax	\$1,000.00
