

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA049 Date of Visit: 5/14/20

Contractor Personnel on Site:

1. Charles Gresham
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

### Service Call Number

CSS# 25096 WO# 12184

### Description of Repairs

Replace/Repair Lights outside of Vaults.

Troubleshoot Light in Hallway working incorrectly.

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Charles Gresham Date: 14 May 20

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Mark Anderson, GS-11 Date: 14 May 20

Signed: 20170

ANDERSON.MARK.STEPHEN.10328  
Digitally signed by  
ANDERSON.MARK.STEPHEN.1032820170  
Date: 2020.05.14 12:37:40 -04'00'

E-Mail: mark.s.anderson7.mil@mail.mil





REST  
EFIG  
THE  
FF  
RC  
I  
TA  
REPR  
A  
UNA



THIS FACILITY IS PROTECTED  
BY AN  
ALARM SYSTEM

**RESTRICTED AREA  
WARNING**

THIS FACILITY AND BASE SECURITY IS RESTRICTED AREA BY AUTHORITY OF THE COMMANDER IN ACCORDANCE WITH THE PROVISIONS OF THE DIRECTIVE ISSUED BY THE DIRECTORATE OF SECURITY ON 18 AUGUST 1964. PURSUANT TO THE PROVISIONS OF SECTION 21, MATERIAL SECURITY ACT OF 1947, UNAUTHORIZED ENTRY IS PROHIBITED. ALL PERSONS AND VEHICLES ENTERING THIS AREA ARE UNABLE TO SEARCH FOR INFORMATION, PRINTING, NOTES, DRAWINGS, MAPS OR GRAVURE REPRESENTATIONS OF THIS AREA OR ITS ACTIVITIES. IF PROHIBITED UNLESS SPECIFICALLY AUTHORIZED BY THE COMMANDER IN CHIEF, AND SUCH MATERIAL FOUND IN THE POSSESSION OF UNAUTHORIZED PERSONS WILL BE FORFEITED.



## **RESTRICTED AREA WARNING**

THIS FACILITY HAS BEEN DECLARED A RESTRICTED AREA BY AUTHORITY OF THE COMMANDER IN ACCORDANCE WITH THE PROVISIONS OF THE DIRECTIVE ISSUED BY THE SECRETARY OF DEFENSE ON 20 AUGUST 1954, PURSUANT TO THE PROVISIONS OF SECTION 21, INTERNAL SECURITY ACT OF 1950. UNAUTHORIZED ENTRY IS PROHIBITED. ALL PERSONS AND VEHICLES ENTERING HEREON ARE LIABLE TO SEARCH. PHOTOGRAPHING, MAKING NOTES, DRAWINGS, MAPS OR GRAPHIC REPRESENTATIONS OF THIS AREA OR ITS ACTIVITIES, IS PROHIBITED UNLESS SPECIFICALLY AUTHORIZED BY THE COMMANDING OFFICER. ANY SUCH MATERIAL FOUND IN THE POSSESSION OF UNAUTHORIZED PERSONS WILL BE CONFISCATED.

