

Additional Funding Request

VA011	CSS# 25659 WO# 11977 Asset# 190918-207			
Description of Repairs	Repair and retest Back Flow			
Diagnosis: Initial Work Order	Back flow failed certification and needs to be repaired and re-certified			
Diagnostic Fee	\$ 120			
Additional Labor Cost to Perform Repairs	\$ 840 Labor \$120/hr x 7			
Additional Cost	\$ 562.95			
	Retest Backflow fee	1	\$155.00	\$115.00
	Repair Back Flow Kit	1	\$394.95	392.95
	Truck Fee			55.00
CM CREDIT	(\$250.00)			
Total Cost of Repair	\$ 1,272.95			



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

July 29, 2020

Quotes are valid for 30 days.

USARC - VA # 011 Culpeper
1821 Industry Street
Culpeper, VA 22701
Email

tina.lee@tideh2o.net

Contact Name Tina Lee & Adam Colopy
Telephone N/A
Cell Phone 614-623-9569
Fax Number N/A

DESCRIPTION OF EQUIPMENT:

Backflow

DESCRIPTION OF PROBLEM:

Moore's technician Brad Williams was dispatched to site on 2-28-20 and performed backflow test and device failed. Submitting quote for repair and retest.

DESCRIPTION OF REPAIRS:

Moore's recommends technician return to site and repair and retest backflow. **Customer is responsible for any and all non-returnable items and/or restocking charges that apply should the quote be cancelled by the customer, or the scope of work changes in anyway after Moore's has received approval. **

MATERIAL, EQUIP OR PARTS

	Quantity	Sell price
Retest Backflow fee	1.00	\$ 115.00
Repair backflow kit	1.00	\$ 392.95
Truck Fee	1.00	\$ 55.00
Material Total		\$ 562.95

LABOR ITEMIZED

			Labor
Labor - Incurred	1	\$ 120.00	\$ 120.00
Labor - One Man	7	\$ 120.00	\$ 840.00
		Labor Total	\$ 960.00

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$ 562.95
Labor	\$ 960.00
TOTAL	\$ 1,522.95

*This does not include
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591
Ian Harris, Estimator 434-309-2497
James Davis, Estimator 434-309-2568
Marvin Slaughter, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Manassas, VA
Lynchburg, VA • Richmond, VA • Raleigh, NC • Charlotte, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
Customer: TIDEWATER, INC Address: 6625 SELNICK DRIVE ELKRIDGE MD 21075 Phone: 614-623-9569	Customer: USARC VA011 CULPEPER Address: 1821 INDUSTRY STREET CULPEPER VA 22701 Phone: 6146239569
Service Call #: COM0126611	Call Type: COM-PLMB


Service Requested
WO 11683 1-pc Backflow DeviceMech Watts 909 S# 454515 ASSET # 190918-207 PM# PMA190918207 02/21/20BW: EMAILED TINA TO SCHEUDLE FOR 02/25 @ 9A // TINA CAME BACK WITH APPROVAL FOR 02/28 @ 9A

Problems					
Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
BACKFLOW TEST	BRADWILLIA				

Tech Notes
Tech: BRAD WILLIAMS, Date: 2/28/20 9:31 AM - Drove to site and checked in with Christopher. Found back flow device in mechanical room and performed annual test. Device failed due to relief valve not opening and #2 check valve failing. Per existing tag on device, the last time it was tested was 4/26/12 and it failed then as well for same reasons. Will quote to install complete rebuild kit. Did paperwork and checked out.

Labor			
Date	Technician	Description	Hours
2/28/2020	BRAD WILLIAMS	REGULAR PLUMBING LABOR	1.50
2/28/2020	BRAD WILLIAMS	COMMERCIAL TRAVEL TIME	1.00

Materials			
Date	Part Number	Description	Quantity
No records found			

Signed By Christopher Chipps	Signature 	Date 2/28/2020
-------------------------------------	---	-----------------------

Brad Williams

From: Ryan.Reed@Ferguson.com
Sent: Monday, March 2, 2020 7:43 AM
To: Ryan.Reed@Ferguson.com
Subject: Email Bid# B154951

Price Quotation # B154951

FERGUSON ENTERPRISES LLC #31

505 GARRETT STREET
CHARLOTTESVILLE, VA 22902-5693

Phone : 434-971-7000
Fax : 434-977-5586

Bid No.: B154951

Bid Date: 03/02/20

Quoted By: RAR

Customer: MOORES ELECT & MECH CONST INC
MOORES MAIN ACCOUNT
101 EDGEWOOD AVENUE
PO BOX 119
ALTAVISTA, VA 24517

Cust PO#: WATTS 909 REBLD KIT

Cust Phone: 434-369-4374

Terms: 2% 10TH NET 25TH

Ship To: MOORES ELECT & MECH CONST INC
MOORES MAIN ACCOUNT
101 EDGEWOOD AVENUE
PO BOX 119
ALTAVISTA, VA 24517

Job Name: USARC CULPEPER (1)

Item	Description	Quantity	Net Price	UM	Total
WDRK909TTC	LFNP 3/4" T-LPRK 909-T REF KIT	1	310.976	EA	310.98
	1 DAY LEAD TIME				

Subtotal: \$310.98

Inbound Freight: \$0.00

Tax: \$16.48

Order Total: \$327.46

Quoted prices are based upon receipt of the total quantity for immediate shipment (48 hours). SHIPMENTS BEYOND 48 HOURS SHALL BE AT THE PRICE IN EFFECT AT TIME OF SHIPMENT UNLESS NOTED OTHERWISE. QUOTES FOR PRODUCTS SHIPPED FOR RESALE ARE NOT FIRM UNLESS NOTED OTHERWISE.

CONTACT YOUR SALES REPRESENTATIVE IMMEDIATELY FOR ASSISTANCE WITH DBE/MBE/WBE/SMALL BUSINESS REQUIREMENTS.

Seller not responsible for delays, lack of product or increase of pricing due to causes beyond our control, and/or based upon local, state and federal laws governing type of products that can be sold or put into commerce. This Quote is offered contingent upon the Buyer's acceptance of Seller's terms and conditions, which are incorporated by reference and found either following this document or on the web at <https://www.ferguson.com/content/website-info/terms-of-sale>. Govt Buyers: All items quoted are open market unless noted otherwise.

LEAD/FREE WARNING: It is illegal to install products that are not "lead free" in accordance with US Federal or other applicable law in potable water systems intended for human consumption. Products with *NP in the description are NOT