

**Region:** 5

**Location:** VA099

**CSS #:** 25803

**Maximo Work Order No.:** 12467

**Asset #:** NA

**Date Issued:** 7/07/20

**Original Description:** #2 PHWP pump snapped off from piping

**Repairs Needed:**

Labor and materials to replace pump that snapped off from piping. Note this pump has to be custom made and has a 5 week lead time.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

| Quantity | Line Item Number | Description                        | Labor Hours | Labor Rate/Hr | Materials  | Equipment | Total      |
|----------|------------------|------------------------------------|-------------|---------------|------------|-----------|------------|
| --       | NA               | Materials<br>(See attached Detail) | --          | --            | \$2,563.76 | --        | \$2,563.76 |
| --       | NA               | TW Diagnostic                      | 6           | \$80.00       | --         | --        | \$450.00   |
| --       | NA               | TW Labor                           | 12          | \$80.00       | --         | --        | \$960.00   |

**Estimate Summary:**

| Labor Hours | Labor Cost | Material Cost | Equipment | Total Cost | CE Factor | Total Estimate    |
|-------------|------------|---------------|-----------|------------|-----------|-------------------|
| 18          | \$1,410.00 | \$2,563.76    | --        | \$3,973.76 | 106%      | <b>\$4,212.19</b> |



# WORK ESTIMATE

CSS #: 25803

Work Order #: 12467

Emergency ☐

Urgent ☒

Routine ☐

|                         |  |   |       |
|-------------------------|--|---|-------|
| Company Name:           | Tidewater, Inc.  | Facility ID:                                | VA099 |
| Contractor POC:         | Adam Colopy  |   |       |
| Telephone No:           | 740-819-6207   | Building/Location; (e.g., Classroom/Room #) | Mech  |
| E-Mail Address:         | <a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a> |   |       |
| Assigned Technician(s): | Richard Walker   |   |       |

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace pump that snapped off from piping. Note this pump has to be custom made and has a 5 week lead time.

| LABOR/MATERIAL        |          | MATERIAL/<br>SUB UNIT<br>DOLLAR<br>AMOUNT | LBR/HR<br>\$80 | LINE ITEM<br>TOTAL<br>DOLLAR<br>AMOUNT |
|-----------------------|----------|---|----------------|--|
| ITEM                  | QUANTITY |   |                |  |
| Labor                 |          |   | 12             | \$960.00                               |
| Bell and Gossett Pump | 1        | \$2,547.64                                |                | \$2,547.64                             |
| Shipping              | 1        | \$16.12                                   |                | \$16.12                                |
|                       |          |   |                | \$0.00                                 |
| Diagnostic Labor      |          |   | 6              | \$450.00                               |
| SUB-TOTAL COSTS:      |          | Materials Total                           | \$2,563.76     | Labor \$1,410.00                       |
| TOTAL                 |          |   | \$3,973.76     |  |



# Customer Quotation.

| Ship To:  | Information                                 |
|---|---|
| TIDEWATER INC   | Grainger Quote Number 2045023910            |
| 6625 SELNICK DR #A  | Print Date 08/03/2020                       |
| ELKRIDGE, MD 21075-6220   | Customer Account 885295220                  |
| US  | Department Number                           |
| Shipper Account:  | Contact Name RICHARD WALKER                 |
|   | Contact Phone 8049447010                    |
|   | Contact Fax                                 |
|   | Contact Email richard.walker@tideh2o.net    |
|   | Requested by Taylor                         |
|   | Requestor Phone No. StClair                 |
|   | Requestor Fax                               |
|   | Requestor Email Taylor.StClair@grainger.com |
| <b>eQuote Information:</b><br>Quote 2045023910 has been delivered to Grainger websites and Richard Walker has been notified via email that the quote is available for on-line purchasing. |   |

**Comments:** Prior authorization is required for ALL returns; product must be new/unused and in original packaging. All returns may be subject to a restocking fee, assessed by the supplier upon inspection. Customer is responsible for return-shipping costs.

| Line | Description   | MFG Part No        | Lead Time Bus.days | Qty. | Unit | Quote Price | Extended Price |
|------|---|--------------------|--------------------|------|------|-------------|----------------|
| 10   | 1.25X5.25, 1/2HP, 5"IMP, 1PH<br>Mfr Brand Name XYLEM-BELL & GOSSETT<br>Customer Part No.:<br>Carrier: 29811 - UPS GROUND<br>Cost expiration date: 09/03/2020<br>Taxable: YES                              | E-6011/4X51/41/2HP | 25                 | 1    | EA   | 2,021.94    | 2,021.94       |
| 20   | -- NO QUOTE -- SEE ITEM NOTES FOR DETAILS --SERIES E-60 CROSS<br>Mfr Brand Name XYLEM-BELL & GOSSETT<br>Customer Part No.:<br>Cost expiration date:<br>Taxable: NO<br>Notes: New part# E-6011/4X51/41/2HP | C158802-02         |                    | 1    | EA   | 0.00        | 0.00           |

Thank You!  
Call or visit us at  
401 S. Wright Rd  
Janesville, WI 53546  
www.grainger.com  
(800)472-4643

Information

Grainger Quote Number 2045023910  
Print Date 08/03/2020  
Customer Account 885295220  
Page 2 / 2

Estimated Freight 16.12  
Total Sell Price in USD 2,038.06

This is not an invoice. Changes to product or quantities may result in different pricing. Availability and lead times are subject to change and can be confirmed at order placement. Additional lead time may apply for AK and HI. Unless otherwise stated, these items are sold for domestic consumption in the United States. If exported, purchaser assumes full responsibility for compliance with U. S. export control. Contact Sales Rep.or Grainger branch listed below for questions, order placement or to submit a new request. **Return Policy: Please contact Grainger before returning any product. All returns are subject to the manufacturer's return policy. Special Order items may not be returnable. Restocking fees may apply.**

Thank You!  
Call or visit us at  
401 S. Wright Rd  
Janesville, WI 53546  
www.grainger.com

(800)472-4643



Scroll capture



Draw



Crop



Share









