

Additional Funding Request

MD002	CSS# 25885 WO# 14162 05/11/21							
Description of Repairs	Labor to cut back and re-mud the cracks, sand and paint.							
Diagnosis: Initial Work Order	Repair several settlement cracks in ceiling throughout 1st floor female latrine, bldg 001. Patch, sand, paint to match.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 640</p> <p>Labor \$80/hr x 8</p>							
Additional Material Cost to Perform Repairs	<p>\$ 0</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Parts</td> <td style="width: 25%; text-align: center;">1</td> <td style="width: 25%; text-align: center;">0</td> <td style="width: 25%; text-align: center;">0</td> </tr> </table>				Parts	1	0	0
Parts	1	0	0					
Total Cost of Repair	\$ 800.00							



WORK ESTIMATE

CSS #:

25885

Work Order #:

14162

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Cology		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.cology@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor to cut back and remud the cracks, sand and paint.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Labor			8	\$640.00
SUB-TOTAL COSTS:		Materials Total	\$0.00	Labor \$800.00
		TOTAL	\$800.00	