

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MJ 002

Date of Visit: 7/16/20

Contractor Personnel on Site:

1. Casey Davis
2. _____
3. _____

4. _____
5. _____
6. _____

Service Calls – Service Call Number and Description

Wet# 1. 124173 ESS#25910
Bldg# 3141 A/C Repair . Ex Fan Repair

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Casey Davis

Date: 7/16/20

Signed: Casey Davis

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: _____

E-Mail: _____



CU-01





A WARNING

HAZARD OF VOLTAGE

DISCONNECT ALL ELECTRICITY
INCLUDING REMOTE POWER
FOLLOW LOCK OUT AND
TAG OUT PROCEDURES
PROVIDED BY MANUFACTURER

INSURE THAT ALL MOTOR CAPACITORS HAVE BEEN
DISCHARGED AND THAT THERE IS NO
STORED VOLTAGE. UNITS WITH VARIABLE SPEED
DRIVES MAY CONTAIN CAPACITORS WHICH
REMAIN CHARGED LONG AFTER THE
DRIVE HAS BEEN TURNED OFF.
REFER TO DRIVE INSTRUCTIONS FOR CHARGING
PROCEDURES. FAILURE TO DO THE ABOVE COULD RESULT
IN SERIOUS INJURY.

AVERTISSEMENT

DANGER DE TENSION

DÉSÉLECTEZ TOUTES LES
ÉLECTRIFICATIONS,
Y COMPRIS LE PUISSANCE
ÉLECTRIQUE
ÉLECTRONIQUE.
SUIVEZ LES PROCÉDURES
DE SÉCURITÉ
DEVERROUILLAGE ET
DÉSIGNIFICATION
PROVIDÉES PAR
LE FABRICANT.

AVERTISSEMENT

DANGER DE TENSION

DÉSÉLECTEZ TOUTES LES
ÉLECTRIFICATIONS,
Y COMPRIS LE PUISSANCE
ÉLECTRIQUE
ÉLECTRONIQUE.
SUIVEZ LES PROCÉDURES
DE SÉCURITÉ
DEVERROUILLAGE ET
DÉSIGNIFICATION
PROVIDÉES PAR
LE FABRICANT.