

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: \_\_\_\_\_ Date of Visit: 4/19/21

Contractor Personnel on Site:

- |          |          |
|----------|----------|
| 1. _____ | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

**Service Call Number**

CSS# \_\_\_\_\_ WO# \_\_\_\_\_

**Description of Repairs**

---

---

---

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: Richard Walker

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: Christina Wingan

E-Mail: \_\_\_\_\_



SIEMENS  
3RT1000-0AB0  
125A 250V  
3-Phase Thermal Relay  
Type: 3RT1000-0AB0  
Rating: 125A 250V  
Dimensions: 100x100x100mm  
Weight: 1.5kg  
Made in Germany

SIEMENS  
3RT1000-0AB0  
125A 250V  
2-Phase Thermal Relay  
Type: 3RT1000-0AB0  
Rating: 125A 250V  
Dimensions: 100x100x100mm  
Weight: 1.5kg  
Made in Germany

SIEMENS  
3RT1000-0AB0  
125A 250V  
3-Phase Thermal Relay  
Type: 3RT1000-0AB0  
Rating: 125A 250V  
Dimensions: 100x100x100mm  
Weight: 1.5kg  
Made in Germany



power comes in, but not out of heat coil contactor

