

Additional Funding Request

DE001	CSS# 26875 WO# 13175 Asset# NA							
Description of Repairs	Labor and material to replace door closer							
Diagnosis: Initial Work Order	The door closer on the man door next to the overhead door in the drill hall has detached from the door frame and needs to be reconnected. Unsure if the existing is still usable.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 320</p> <p>Labor \$80/hr x 4</p>							
Additional Material Cost to Perform Repairs	<p>\$ 153.09</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Norton Door Controls Manual Hydraulic Door Closer Heavy Duty Interior and Exterior</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">153.09</td> <td style="width: 10%; text-align: center;">153.09</td> </tr> </table>				Norton Door Controls Manual Hydraulic Door Closer Heavy Duty Interior and Exterior	1	153.09	153.09
Norton Door Controls Manual Hydraulic Door Closer Heavy Duty Interior and Exterior	1	153.09	153.09					
Total Cost of Repair	\$ 633.09							



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	DE001
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and equipment to replace door closer.

LABOR/MATERIAL		MATERIAL/SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			4	\$320.00
Norton Door Controls Manual Hydraulic Door Closer, Heavy Duty, Interior and Exterior	1	\$153.09		\$153.09
				\$0.00
				\$0.00
				\$0.00
				\$0.00
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$153.09	Labor \$480.00
		TOTAL		\$633.09

Compare

NORTON DOOR CONTROLS

Manual Hydraulic Door Closer, Heavy Duty, Interior and Exterior



Item # **1RM12**

Mfr. Model # **1601BFXAL**

Catalog Page # **1990**

[View Product Details](#)

Web Price i

\$121.50 / each

Availability

Expected to arrive **Mon. Dec 28.**

[Ship to 21162](#) ▾

Qty

1

Add to Cart





