

Additional Funding Request
INVOICE

DE007	CSS# 27669 WO# 13298 Asset# NA							
Description of Repairs	Incurred cost for S&S Mechanical.							
Diagnosis: Initial Work Order	There seems to be a problem with the breakers tripping out for some of the exterior pole lights at the center. This is a new issue and could have possibly been caused by the construction going on, on the other side of the property.							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 1200</p> <p>SS \$100/hr x 12</p>							
Additional Cost	<p>\$ 0</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">N/A</td> <td style="width: 25%;">1</td> <td style="width: 25%;"></td> <td style="width: 25%;"></td> </tr> </table>				N/A	1		
N/A	1							
Total Cost of Repair	\$ 1200							



PLEASE PAY BY	AMOUNT	INVOICE DATE
04/25/2021	\$1,200.00	03/26/2021

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

INVOICE NO. 82369

Job Name: 13298
Site: DE007 Olgetown Road
Site Address: 1001 Ogletown Road
 Newark DE 19711

Description

WO#: 13298

CSS Ticket Number: 27669

Problem: There seems to be a problem with the breakers tripping out for some of the exterior pole lights at the center. This is a new issue and could have possibly been caused by the construction going on, on the other side of the property.

12/09/2020 Work Note

Upon arrival contacted POC Danielle and gained access to the mechanical room where panel is for outside lighting. Breakers were off. Not tripped. Turned breakers on and turned on lights at the timer. Observed outside that lights did come on. Went back in and waited 30-45 minutes to see if breakers tripped. No breakers tripped and lighting worked fine. All power was correctly hooked up. No sign of arking or burn marks anywhere. All poles had correct power.

12/10/2020 Work Note

Today the breakers tripped. Upon inspection I found that phases were wired wrong on contactor. I fixed the wiring and now only circuit 19 is tripping. Before this light construction across the parking lot has dug up the ground to tie into the sewer system. I believe this is the cause for circuit 19 breaker tripping. Left circuit 19 off. All other lights are operable. We will have to run new wire from the second to last pole to the last pole in that run. Where the construction company has dug up the ground and tied into the sewer will need dug back up to fix broken pvc before running new wire. Will probably need a crane to pick light pole as whoever ran circuit did not leave enough in the bottom of light pole to work with. Upon repair of circuit we can then evaluate what lights needs new bulbs and ballasts.

7301 - Service

Item	Quantity	Unit Price	Total
Electrical Labor Rate	12.00 hrs	\$100.00	\$1,200.00
		Labor	\$1,200.00
		Sub-Total ex Tax	\$1,200.00

Make all checks payable to S&S Mechanical. Overdue accounts are subject to a service charge of 1.5% per month. Thank you for your business.

-S&S Mechanical also accepts all major credit cards. Call 301-574-1555 to pay an invoice via credit card-

Sub-Total ex Tax	\$1,200.00
Tax	\$0.00
Total inc Tax	\$1,200.00
Amount Applied	\$0.00
Balance Due	\$1,200.00



