

Additional Funding Request

INVOICE

VA050	CSS# 28060 WO# 13329 Asset# NA			
Description of Repairs	While onsite diagnosing issue, found Front Entrance Reader to be nonfunctional. Replaced reader while on site as per Rick Hicks approval.			
Diagnosis: Initial Work Order	Repair CAC system that is not allowing FC to create HID cards for contractors.			
Diagnostic Fee	\$ 0			
Additional Labor Cost to Perform Repairs	\$ 150 LoCurrent \$75 x 2 men/ 1 hour			
Additional Cost	\$ 0			
	Biometric Reader	1	1,450.00	1,450.00
	Core Rebate	1	-200.00	-200.00
	Admin Fee	1	50.00	50.00
Total Cost of Repair	\$ 1450.00			

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



INVOICE

BILL TO

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

INVOICE # 1829
DATE 01/11/2021
DUE DATE 02/10/2021
TERMS Net 30

P.O. NUMBER

VA050Strathmore Diag Guest Pass

ACTIVITY	QTY	RATE	AMOUNT
Services	1	1,450.00	1,450.00
As per Estimate #1714: CSS#28060 WO#13329 Richmond, VA Strathmore VA050 Diagnose Guest Pass			

Dear Ms. Lowery:

As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose the Guest Pass at the Richmond VA050 Strathmore Facility.

While on site diagnosing issues, found Front Entrance Reader to be nonfunctional. Replaced Reader while on site as per Rick Hick's approval.

Cost Breakdown:

(2) men 1 hr @ \$75.....\$150.00
Please note: lowered man time from (2) men 3 hours to (2) men 1 hr as a courtesy as we were on site performing separate work.
(1) Biometric Reader.....\$1,450.00
Core Rebate.....\$200.00
Administrative.....\$50.00

Grand Total.....\$1,450.00

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300.

BALANCE DUE

\$1,450.00

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VAOSO Date of Visit: 1-8-21

Contractor Personnel on Site:

- | | |
|-------------------------|----------|
| 1. <u>Keith Pearson</u> | 4. _____ |
| 2. <u>Chris Denike</u> | 5. _____ |
| 3. _____ | 6. _____ |

Service Calls – Service Call Number and Description

1. EST - 1714
2. CSS - 28060
3. WO - 13329

Diagnosed Defective Reader @ main Entrance
replaced w/new

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Keith Pearson Date: 1-8-21

Signed: [Signature]

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: CPT. T. Friend Date: 1-8-21

Signed: [Signature]

E-Mail: thessolunia.m.friend.mil@mail.mil

LOW FORMS



PLACE FINGER

ENTER

PLACE
CARD

NO
ENTRY

1

2

3

4

5

6

7

8

9

*

0

#

INSERT CARD

Gain Entrance

ION OF WORK

for:
th Pearce

Strathmore

VA

Bio Not Working

KP 1-8-21