

Additional Funding Request

DE007	CSS# 28154 WO# 13437 Asset# NA						
Description of Repairs	S&S Additional efforts for boilers not working properly from work order 13434						
Diagnosis: Initial Work Order	No heat, boilers down; additional efforts, labor						
Diagnostic Fee	\$ 0						
Additional Labor Cost to Perform Repairs	\$ 2000 Labor \$100/hr x 20						
Additional Material Cost to Perform Repairs	\$ 210.00 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Blower Motor</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: center;">210</td> <td style="width: 20%; text-align: center;">210</td> </tr> </table>			Blower Motor	1	210	210
Blower Motor	1	210	210				
Total Cost of Repair	\$ 2210.00						



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 466

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 13437
Quote No: 466
Site: DE007 Olgetown Road
Site Contact:
Salesperson: Molly King
Created Date: 12/18/2020
Valid For: 30 Day(s)

S&S additional efforts for boilers not working properly from work order 13434

Service

Item	Quantity	Unit Price	Total
Blower Motor	1.00	\$210.00	\$210.00
HVAC Labor Rate	20	\$100.00	\$2,000.00
Sub-Total ex Tax			\$2,210.00
Tax			\$0.00
Total inc Tax			\$2,210.00

Labor	\$2,000.00
Materials	\$210.00
Sub-Total ex Tax	\$2,210.00
Tax	\$0.00
Total inc Tax	\$2,210.00
