

DOUG MOORE

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: M0003

Date of Visit: 1/25/21

Contractor Personnel on Site:

1. Doug Moore
2. _____
3. _____
4. _____
5. _____
6. _____

Service Calls – Service Call Number and Description

1. install Boiler Board and Test
2. _____
3. _____

WO# 13449

CS# 28224

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Doug Moore Date: 1/25/21

Signed: Doug Moore

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Nicholas R Cruz SGT Date: 1/25/21

Signed: Nicholas R Cruz

E-Mail: nicholas.R.Cruz5.mil@mail.mil

SAFe40 V4 everp"US" 120V ~ 60Hz IP 00

Ser.-Nr. 2530-920-700019-8738803949
Version 07

WARNING

Electrical hazard.
Follow lockout/tagout
procedure when
servicing this boiler.



AVERTISSEMENT

Hazard électrique.
Suivez la procédure de
verrouillage/ étiquetage quand vous
faites l'entretien de la chaudière.

Datum Schlüssel-Nr.

34919094

5JTW

105°C

EG0165

LL527855 FT2 QX30

SA4940-L003840
120V ~ 60Hz IP 00
Ser. N. 2500-003-300018-747013297
Version 0.1



WARNING



Electrical hazard.
High voltage output
protective when
servicing this boiler.




AVERTISSEMENT



Hazard électrique.
Suivez la procédure de
débranchement/équipotentialité de
l'appareil/équipotentialité de
l'entretien de la chaudière.

Ionisation
PWM
+ PWM



63030447

BUS

derus