

Region: 5

Location: VA050

CSS #: 28777

Maximo Work Order No.: 13632

Asset #: NA

Date Issued: 2/9/21

Original Description: The gate is not working will not open and when you push to open it starts grinding, FC opens it manually to prevent further damage.

Repairs Needed:

LoCurrent proposes to replace the year old Gate Operator which has been experiencing functionality issues for quite some time with new. Contractor shall re-use existing Base-rise, Drive rail system, wiring

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	LoCurrent Total See attached Detail	16	--	--	--	\$20,619.51
--	NA	TW Coordination Labor	4	80	--	--	\$320.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
20	\$320.00	\$20,619.51	--	\$20,939.51	106%	\$22,195.88

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
 6625- A Selnick Drive
 Elkridge, MD 21075

ESTIMATE # 1727**DATE** 02/03/2021**P.O. NUMBER**

Richmond, VA050 Replace Gate Op

	ACTIVITY	QTY	AMOUNT
02/03/2021	Services Richmond, VA AFRC Strathmore USARC VA050 Replace Gate Operator CSS# 28777 WO# 13632	1	20,619.51

Dear Ms. Lowery:

As per your request, LoCurrent Systems is please to provide a quotation to replace the 6 year old Gate Operator which has been experiencing functionality issues for quite some time with new. Contractor shall re-use existing Base-rise, Drive Rail System, Wiring.

Cost Breakdown: (See attached Spreadsheet)

The cost for the above mentioned work is \$20,619.51.

If acceptable, please do not hesitate to contact us so that we may get all equipment and materials on order.

Thank you so much for thinking of LoCurrent Systems.

Sincerely,

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		
	TOTAL	\$20,619.51

Accepted By

Accepted Date

Pricing Summary

Richmond, VA USARC Gate Operator Replacement

Richmond, VA USARC VA050



1084 Federal Road
Brookfield, CT 06804
USA

LoCurrent Systems LLC

3522 County Hwy 11

Cooperstown NY 13326
USA

Original

Document Number

104182

SALES QUOTATION

Document Date

04/27/22

Page

1/2

Customer No.

C01815

Your Reference

Bryan

Your Contact

Paul Cardillo

914-698-5083

paul@powerdoorproducts.com

Delivery Address

LoCurrent Systems LLC

Same as Bill-to

Currency: \$

		Quantity	UoM	Price	Tax %	Total
001	Item Code: 222 SS ST	1		10,637.55	8.00	10,637.55
"Hy-Security Slide Gate Operator; no brake valves. With IRB-MON Photocell, ASO Edge with Channel, 5"						
002	Item Code: SD-6-01	1		661.50	8.00	661.50
"Heater with thermostat, 230V Installed"						
003	Item Code: MX001224	1		328.65	8.00	328.65
Snow Scraper & Brush Kit-uninstalled						
004	Item Code: SD-C-04	1		283.50	8.00	283.50
"Xtreme Drive System, 6"""						
005	Item Code: MX002599	10		70.00	8.00	700.00
"Xtreme rack kit, 25"" with hardware"						
006	Item Code: MX001033	1		993.88	8.00	993.88
"Base Extension & Hardware 12"", SlideDriver"						
007	Item Code: MX3885	3		420.00	8.00	1,260.00
Drive Rail, Aluminum, grooved, no flange, 14 FT						
008	Item Code: OM-1	1		0.00	8.00	
Photocell						

Carry Over: **14,865.08**

Power Door Products, Inc.

1084 Federal Road

Brookfield CT 06804
USA**Original**

Document Number

104182**SALES QUOTATION**

Document Date

04/27/22

Page

2/2

Currency: \$

Carry Over: **14,865.08**

	Quantity	UoM	Price	Tax %	Total
009	Item Code: HY-5B 2.0	2	201.60	8.00	403.20
"Vehicle detector, automatic (New 6/19)"					
010	Item Code: DSI/120	1	373.23	8.00	373.23
500 Ft. Spool loop wire					
011	Item Code: MS-Q-SL-B-C	1	513.66	8.00	513.66
"MS Loop sealant, quart, black, Case (12)"					
012	Plus shipping as needed				

Quotation Subtotal: **\$ 16,155.17**Total Before Tax: **\$ 16,155.17**Total Tax Amount: **\$ 1,292.42****Total Amount:** **\$ 17,447.59****Quotation Valid Until: 05/27/22****Additional Expenses**

Shipping Type:

Payment Term**Net 30**