

## Additional Funding Request

<b>NY039</b>	<b>CSS# 29486 WO# 12286 Asset# NA</b>						
Description of Repairs	Labor and materials to replace 2 magnetic motor starts and 2 check valves to repair sump pump.						
Diagnosis: Initial Work Order	Repair sump pump. Pump has a bad contactor.						
Diagnostic Fee	\$ 160 Labor \$80/hr x 2						
Additional Labor Cost to Perform Repairs	\$ 880 Labor \$80/hr x 11						
Additional Material Cost to Perform Repairs	\$ 1275.92 <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 5px;"> <tr> <td style="width: 50%;">Parts (see attached detail)</td> <td style="width: 10%; text-align: center;">2</td> <td style="width: 20%; text-align: right;">1275.92</td> <td style="width: 20%; text-align: right;">1275.92</td> </tr> </table>			Parts (see attached detail)	2	1275.92	1275.92
Parts (see attached detail)	2	1275.92	1275.92				
Total Cost of Repair	\$ 2315.92						



# WORK ESTIMATE

CSS #:

29486

Work Order #:

12286

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.	Facility ID:	NY039
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>		
Assigned Technician(s):	Patrick Brown		



## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and material to replace 2 magnetic motor starters, and 2 check valves to repair sump pump.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagostic			2	\$160.00
Eaton Nemo Magnetic Motor Starter	2	\$511.79		\$1,023.58
Check Valve, 2 inch	2	\$126.17		\$252.34
Labor			11	\$880.00
SUB-TOTAL COSTS:		Materials Total	\$1,275.92	Labor \$1,040.00
TOTAL			\$2,315.92	



# Cart

Item	Quantity	Total Price	Item Availability
 <b>EATON NEMA Magnetic Motor Starter, 208V AC Coil Volts, Overload Relay Amp Setting: 4 to 20A</b> Item #6LDE2 Your Price: <b>\$399.84</b>	2	<b>\$799.68</b>	Expected to arrive <b>Thu. Apr 1</b> using standard ground shipping (additional shipping options available at Checkout.)
 <b>GRAINGER APPROVED Check Valve, 2 in, Single, Inline Swing, Bronze, FNPT x FNPT</b> Item #10F295 Your Price: <b>\$98.57</b>	2	<b>\$197.14</b>	Expected to arrive <b>Wed. Mar 31</b> using standard ground shipping (additional shipping options available at Checkout.)



Chat with an Agent







208V60CY

**CUTLER • HAMMER**

SERIES A1

**NEMA SIZE 0**

MAX 3 PH RATINGS

18 AMP	115V.....	2 HP
	200/230V.....	3 HP
	460/575V.....	5 HP

M


208V60CY

1997 E

**CUTLER • HAMMER**

No. A10BNO

SERIES A1



**NEMA SIZE 0**

PARTS PUB A10B-1

CONTACT KIT 6-22-2

MADE IN USA

MAX 3 PH RATINGS

18 AMP	115V.....	2 HP
	200/230V.....	3 HP
	460/575V.....	5 HP

2M





