

Additional Funding Request

MD002	CSS# 29656 WO# 115392							
Description of Repairs	Tidewater proposes labor and materials to remove and replace 25 stair tread strips.							
Diagnosis: Initial Work Order	Repair main lobby stairwell treads, and exit stairwell treads, bldg 001. Remove existing self-adhesive treads, replace with same style/type.							
Diagnostic Fee	\$ 160 Labor \$80/hr x 2							
Additional Labor Cost to Perform Repairs	\$ 480 Labor \$80/hr x 6							
Additional Material Cost to Perform Repairs	\$ 219.55 <table border="1"><tr><td>3M Safety-Walk Slip Resistant Step and Reflective Tread 6" x 2"</td><td>25</td><td>6.97</td><td>219.55</td></tr></table>				3M Safety-Walk Slip Resistant Step and Reflective Tread 6" x 2"	25	6.97	219.55
3M Safety-Walk Slip Resistant Step and Reflective Tread 6" x 2"	25	6.97	219.55					
Total Cost of Repair	\$ 859.55							



WORK ESTIMATE

CSS #: 29656

Work Order #: 15392

Emergency ☐

Urgent ☐

Routine ☒

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to remove and replace 25 stair tread strips.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagostic			2	\$160.00
3M Safety-Walk Slip Resistant Step and Reflective Tread 6" x 2"	25	\$6.97		\$219.55
Labor			6	\$480.00
SUB-TOTAL COSTS:		Materials Total	\$219.55	Labor \$640.00
TOTAL			\$859.55	



**SAFETY-WALK™ SLIP RESISTANT
STEP AND REFLECTIVE TREAD**

6" X 2'

SKU 184-304

**INCREDIBLE TEXTURE HELPS
PREVENT SLIPPING**

3M

3M and Safety Walk are trademarks of 3M. © 3M 2018. 75-0713-2585-4

**3M SAFETY WALK 6" X 2'
REFLECTIVE**

\$6⁹⁷
ea

7768NA
AISLE BAY PK 12
04 003





