



Proposal

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

May 9, 2022

RE:W/O 16882 CSS#32211 NY001

Sump pump

Install Dayton Pump Control Panel.
Replace 9\$0 switching floats and adjust

Relays on existing panel have failed due to old pump that was locked up.

(1) Dayton control panel 2pzg7 Grainger	1321.56	1321.56
(4) switch floats 3by84 USA (Grainger).	148.41	593.64
Misc conduit and wire		75.00

		1990.20.
5hrs @ 600.00.		600.00

sub-total.		2590.20
20%profit/OH		518.04

Total.		3108.24

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL