

Additional Funding Request

MD024	CSS# 32916 WO# 15132						
Description of Repairs	Park Heights Roofing proposes to reattach existing siding where missing.						
Diagnosis: Initial Work Order	Repairs to siding damaged by high winds. Bldg 1003, bayside						
Diagnostic Fee	\$ 0						
Additional Labor Cost to Perform Repairs	\$ 500 Labor \$250/hr x 2						
Additional Material Cost to Perform Repairs	\$ 40 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Nails and caulk</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: right;">40.00</td> <td style="width: 20%; text-align: right;">40.00</td> </tr> </table>			Nails and caulk	1	40.00	40.00
Nails and caulk	1	40.00	40.00				
Total Cost of Repair	\$ 540						

Park Heights Roofing
6999 Reisterstown Rd Suite 1
Baltimore, MD 21215
410-358-1257



Estimate

ADDRESS	SHIP TO	ESTIMATE # 450
Gabby Mascelli	Gabby Mascelli	DATE 10/28/2021
720 East Ordinance Road	720 East Ordinance Road	
BLDG - 1003	BLDG - 1003	
Brooklyn Park, MD 21226	Brooklyn Park, MD 21226	

		AMOUNT
Repair		540.00
720 East Ordinance Building 1003: Reattach existing siding where missing.		
Contractor Signature:	TOTAL	\$540.00

Accepted By

Accepted Date



SAFETY
DIAL 911
IN CASE OF
EMERGENCY