

Additional Funding Request

VA006	CSS# 34455 WO# 16432							
Description of Repairs	Moore's proposes labor and materials to remove and replace the low water cutout controls and gauges for boiler #1 and #2. Once repairs are completed, Moore's will start, test and ensure proper operation of the unit.							
Diagnosis: Initial Work Order	The #1 Boiler is in LOCKOUT due to low water pressure							
Diagnostic Fee	\$ 360 Labor \$120/hr x 3							
Additional Labor Cost to Perform Repairs	\$ 960 Labor \$120/hr x 8							
Additional Material Cost to Perform Repairs	\$ 940.60 <table border="1"><tr><td>Materials (see attached detail)</td><td>1</td><td>940.60</td><td>940.60</td></tr></table>				Materials (see attached detail)	1	940.60	940.60
Materials (see attached detail)	1	940.60	940.60					
Total Cost of Repair	\$ 2,260.60							



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

February 9, 2022

Quotes are valid for 14 days.

USARC - VA006
1634 Cherry Ave Charlottesville VA 22903
PO: 15979
Email lopy@tideh2o.net & Mary.Lowery@tideh2o.net

Contact Name Mary Lowery & Adam Colopy
Telephone 0.00
Cell Phone 614-623-9569
Fax Number 0.00

DESCRIPTION OF EQUIPMENT:

Boiler #1 & 2
Weil Mclain
Model # ULTRA 750

DESCRIPTION OF PROBLEM:

Moore's technician arrived on location, boiler one was down. Found that low water cut off probe is defective and will not close the circuit. I was able to jump that out to allow boiler to run. Manufacturer has three other safeties in place for over temperature and/or low flow applications and will shut Boiler down if this event occurs. Having low water cut off out of the circuit will not affect the boiler operation, this is an add on feature for state or local ordinance and does not affect the overall operation if it's removed from the system during a failure. They have none in stock and will need to be quoted, Repair cost will go over our NTE amount.

DESCRIPTION OF REPAIRS:

Moore's is proposing to return to site and: Remove and replace the low water cutout controls and gauges for boiler #1 and #2. Once repairs are completed, we will start, test and ensure proper operation of the unit.

Parts have an estimated 2-3-week lead time

MATERIAL, EQUIP OR PARTS

	Quantity	Sell price
Low water cut out	2.00	\$ 638.40
Gauge	2.00	\$ 187.20
Freight	1.00	\$ 60.00
Truck Fee	1.00	\$ 55.00
Material Total		\$ 940.60

LABOR ITEMIZED

		Labor
Labor - Incurred	3	\$ 120.00 \$ 360.00
Labor - One Man	8	\$ 120.00 \$ 960.00
Labor Total		\$ 1,320.00

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$ 940.60
Labor	\$ 1,320.00
TOTAL	\$ 2,260.60

Robert Lowery, Changeout Estimator 434-309-2591
Ian Harris, Estimator 434-309-2497
James Davis, Estimator 434-309-2568
Marvin Slaughter, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

In consideration of Moore's Electrical & Mechanical extending credit to the above applicant, the undersigned hereby personally guarantees unconditionally and irrevocably. The compliance of all terms of the application and agreement, including the payment of any sums within the net terms agreed upon between the customer and Moore's, plus any additional costs such as a 1.5% monthly interest charge starting once an invoice becomes 30 days past due, service charges, legal fees and any means taken in order to collect debt. If it is deemed necessary to litigate, it is agreed that the County or District Court of Campbell County, Virginia shall be the venue of any suit. This guarantee shall remain in full force unless and until notice in writing is sent certified mail and received by Moore's Electrical & Mechanical. Said notice cannot be within 14 days of this signed agreement. Initial service request ran with a Not to Exceed amount of \$500.00 (five hundred dollars).

S.E. Burks Sales Company, Inc.

2518 Waco Street
Henrico, VA 23294

Quote

Customer No.: MOORES

Quote No.: 11125

Quote To: **Moores Electric**
P.O. Box 119
Altavista, VA 24517

Ship To: **Moores Electric**
101 Edgewood Ave
Altavista, VA 24517

Date		Ship Via		F.O.B.		Terms	
02/08/2022		Bestway - Add Frt		Origin		Net 30	
Purchase Order Number			Sales Person				Required
			Zach Mitchell				02/08/2022
Quantity			Item Number	Description	Unit Price	Amount	
Required	Shipped	B.O.					
2			383-600-069	Weil Mclain LWCO	266.00	532.00	
2			570-218-054	T&P gauge Weil-Mclain	78.00	156.00	
Quote subtotal						688.00	
Quote total						688.00	


Thank You

MANDATORY WATER TREATMENT - ULTRA GAS
You MUST add the included Sentinel X100 Inhibitor to the system to prevent damage to the boiler's heat exchanger. Follow inhibitor installation instructions and adjust to the proper pH level.

WARNING Failure to comply with installation instructions may result in accelerated corrosion of the heat exchanger and system components.

550225340 (09)

B1



WEIL-McLAIN
2:52 AM 01/01/08

MODULATION IGNITION
INFO

