

## Additional Funding Request

<b>NY051</b>	<b>CSS# 34473 WO# 16302 Asset# NA</b>
Description of Repairs	Labor to investigate IDS System at Oswego USARC
Diagnosis: Initial Work Order	Repair arms vault panel. Panel goes in alarm and reset button is broken, cant reset panel.
Diagnostic Fee	\$ 160 TW Labor \$80/hr x 2
Additional Labor Cost to Perform Repairs	\$ 680 LC Labor \$85/hr x 8
Additional Material Cost to Perform Repairs	\$ 0
<b>Total Cost of Repair</b>	<b>\$ 840</b>

**LoCurrent Systems, LLC**

3522 County Highway 11  
 Cooperstown, NY 13326  
 (607)293-7300  
 locurrent@gmail.com



# Estimate

**ADDRESS**

Tidewater Inc.  
 6625- A Selnick Drive  
 Elkridge, MD 21075

**ESTIMATE #** 1934**DATE** 02/09/2022**P.O. NUMBER**

Oswego, NY USARC Diagnose IDS

	ACTIVITY	QTY	AMOUNT
02/09/2022	<b>Services</b> Oswego, NY USARC Diagnose IDS Issues	1	680.00

Dear Mr. Brown:

As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose and repair if possible the issues being experienced with the IDS System at the Oswego, NY USARC.

Cost Breakdown:

(1) man 8 hrs @  
 \$85.....\$680.00

The cost to diagnose and repair if possible the above mentioned.

If acceptable, please do not hesitate to contact us.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

TOTAL

**\$680.00**

Accepted By

Accepted Date