

DOUG MOORE

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD 002

Date of Visit: 3/30/22

Contractor Personnel on Site:

1. Doug Moore
2. _____
3. _____

4. _____
5. _____
6. _____

Service Calls – Service Call Number and Description

1. Breather check in Building 002 for ACCU#6
2. _____
3. _____

WOT# 16906 CS# 35154

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Doug Moore Date: 3/30/22
Signed: Lug Jr

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Hamill, Brent Date: 30 Mar 22
Signed: Brent H. Hamill

E-Mail: brent.h.hamill.mil@army.mil





10-ACCU-06

Science