

Additional Funding Request

Submitted: **05/27/22**

NY127	CSS 356 WO 17210			
Description of Repairs	Labor and Materials to install a battery pack mounted on the wall above the light in a panel with 90 minutes of backup power.			
Original SC Investigative Diagnosis	\$160			
Diagnosis: Initial Work Order	Repair light outside of Arms Vault			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials: \$ 457.74			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	Materials (See attached for details)	1	457.74	457.74
Additional Labor Cost to Perform Repairs	Labor: \$480 6 hours each/ \$80.00			
Total Cost of Repair	\$1097.74			



Customer Quotation

To:

TIDEWATER INC
6625 SELNICK DR #A
ELKRIDGE MD 21075-6220

Information

Date	05/24/2022
Customer Account Number	885295220
Grainger Quote Number	46792986
Customer Job Number	
Contract Number	
Grainger Representative	John R Romano
Phone Number	
Fax Number	
Email	
Grainger Tax ID	36-1150280

Item	Description Manufacturer Name & Model	Cat. Pg. #	Qty	\$ Quote	Ext. Price	Start Date	Exp. Date
56RU23	Emerg. Lighting Inverter, 10W, 120-277VAC BODINE ELI-S-10 Country of Origin: Mexico		1	275.20	275.20	05/24/2022	09/30/2022
				Total \$	275.20		

All orders are subject to the terms and conditions in your current contract with Grainger or to Grainger's current Terms of Sale as set forth on Grainger.com

Thank You!
Visit us at grainger.com



Cart

Order Summary

Subtotal	\$106.25	Estimated Tax	N/A	Estimated Shipping	FREE
Estimated Total \$106.25					
As a Red Pass Plus member, you're getting FREE standard shipping on this order.					



HOFFMAN
Panel Kit: Steel
Item # 32FF34

Qty
1

Your Price
\$106.25 / each

Availability
Expected to arrive **Fri. May 27.**

Clear Cart

Chat with an Agent

