

## **Additional Funding Request**

Submitted: **05/27/22**

<b>VA048</b>	<b>CSS 660 WO 17782</b>								
Description of Repairs	Labor and Materials replace gate operator hydraulic lines.								
Original SC Investigative Diagnosis	<b>\$0</b>								
Diagnosis: Initial Work Order	Gate making loud noises, closes and opens sometimes.								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$ 324.45</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th> <th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th> <th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th> <th style="text-align: left; padding: 2px;"><b>TOTAL</b></th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;"><b>Materials (See attached for details)</b></td><td style="padding: 2px; text-align: center;"><b>1</b></td><td style="padding: 2px; text-align: center;"><b>324.45</b></td><td style="padding: 2px; text-align: center;"><b>324.45</b></td></tr> </tbody> </table>	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	<b>Materials (See attached for details)</b>	<b>1</b>	<b>324.45</b>	<b>324.45</b>
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>						
<b>Materials (See attached for details)</b>	<b>1</b>	<b>324.45</b>	<b>324.45</b>						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$1360.00</b>            2 men @ 8 hours each/ \$85</p>								
<b>Total Cost of Repair</b>	<b>\$1684.45</b>								

**LoCurrent Systems, LLC**

3522 County Highway 11  
Cooperstown, NY 13326  
(607)293-7300  
locurrent@gmail.com



# Estimate

**ADDRESS**

Tidewater Inc.  
6625- A Selnick Drive  
Elkridge, MD 21075

**ESTIMATE #** 2024**DATE** 05/23/2022**P.O. NUMBER**

Monteith, VA Hydraulic Lines

ACTIVITY	QTY	AMOUNT
<b>Services</b> Monteith, VA VA048 CSS #660 WO#17782 Replace Gate Operator Hydraulic Lines	1	1,684.45

Dear Ms. Lowery:

As per your request, LoCurrent Systems is pleased to provide a quotation to Replace Gate Operator Hydraulic Lines at the Monteith, VA Facility VA048.

Cost Breakdown:

(1) Hose Kit, 3  
Hoses.....\$225.82  
(1) Gallon Hydraulic  
Oil.....\$98.63  
(2) men 8 hours @  
\$85/hr.....\$1,360.00

Grand  
Total.....\$1,684.45

The cost for the above mentioned work is  
\$1,684.45.  
If acceptable, please do not hesitate to  
contact us so that we may schedule for work  
to be completed.

Thank you so much for thinking of LoCurrent  
Systems.

ACTIVITY	QTY	AMOUNT
Sincerely,		
Antonietta LoRusso		
	TOTAL	<b>\$1,684.45</b>

Accepted By

Accepted Date



## HYSECURITY FLUID HYDRAULIC MX000970

Manufacturer: HySecurity Item Number: MX000970 No reviews

---

\$142.00

Quantity

ADD TO CART

---


Share

Tweet

Pin it

G+

1  
Chat with us!



## HySecurity MX001129 - 3 Hose Kit-SlideDriver

★★★★★ [Be the first to review this product](#)

---

**\$194.99**

- SlideDriver 3 Hose Kit • Hydraulic Hose Kit - 22", 25", 30"


AVAILABILITY: **IN STOCK**

### **CONTROL BOARD RETURN POLICY**

THERE ARE NO RETURNS ON CONTROL/CIRCUIT BOARDS. IF THERE IS AN OUT-OF-THE-BOX PROBLEM WITH THE BOARD YOU RECEIVE, YOU MUST CALL US WITHIN TWENTY DAYS OF PURCHASE AT (888) 444-8123 TO OBTAIN AN RMA# SO YOU CAN SHIP THE BOARD BACK TO US AND WE CAN START THE EVALUATION PROCESS. IF YOU DO NOT WISH TO WAIT FOR THIS PROCESS TO RESOLVE, YOU CAN PURCHASE A SECOND BOARD WHICH WILL BE CREDITED BACK TO YOU UPON THE MANUFACTURER'S DETERMINATION OF A WARRANTY ISSUE. IF THE PROBLEM IS NOT COVERED UNDER WARRANTY, YOU ARE RESPONSIBLE FOR ALL CHARGES INCURRED. **MANUFACTURER'S FINDINGS ARE FINAL.** YOU ARE RESPONSIBLE FOR SHIPPING THE ORIGINAL PRODUCT BACK TO US: IF THE MANUFACTURER DETERMINES THERE IS A DEFECT COVERED BY WARRANTY, WE WILL REIMBURSE YOUR SHIPPING FEES (FEDEX/UPS GROUND ONLY). EFFECTIVE 3/1/2013.

We use cookies to make your experience better. To comply with the new e-Privacy directive, we need to ask for your consent to set the cookies. [Learn more.](#)

[ALLOW COOKIES](#)



## HySecurity MX001129 - 3 Hose Kit-SlideDriver

★★★★★ [Be the first to review this product](#)

---

**\$194.99**

- SlideDriver 3 Hose Kit • Hydraulic Hose Kit - 22", 25", 30"

AVAILABILITY: **IN STOCK**

### **CONTROL BOARD RETURN POLICY**

THERE ARE NO RETURNS ON CONTROL/CIRCUIT BOARDS. IF THERE IS AN OUT-OF-THE-BOX PROBLEM WITH THE BOARD YOU RECEIVE, YOU MUST CALL US WITHIN TWENTY DAYS OF PURCHASE AT (888) 444-8123 TO OBTAIN AN RMA# SO YOU CAN SHIP THE BOARD BACK TO US AND WE CAN START THE EVALUATION PROCESS. IF YOU DO NOT WISH TO WAIT FOR THIS PROCESS TO RESOLVE, YOU CAN PURCHASE A SECOND BOARD WHICH WILL BE CREDITED BACK TO YOU UPON THE MANUFACTURER'S DETERMINATION OF A WARRANTY ISSUE. IF THE PROBLEM IS NOT COVERED UNDER WARRANTY, YOU ARE RESPONSIBLE FOR ALL CHARGES INCURRED. **MANUFACTURER'S FINDINGS ARE FINAL.** YOU ARE RESPONSIBLE FOR SHIPPING THE ORIGINAL PRODUCT BACK TO US: IF THE MANUFACTURER DETERMINES THERE IS A DEFECT COVERED BY WARRANTY, WE WILL REIMBURSE YOUR SHIPPING FEES (FEDEX/UPS GROUND ONLY). EFFECTIVE 3/1/2013.

We use cookies to make your experience better. To comply with the new e-Privacy directive, we need to ask for your consent to set the cookies. [Learn more.](#)

[ALLOW COOKIES](#)