

## Additional Funding Request

<b>NY127</b>	<b>CSS# 735 WO# 17645</b>				
Description of Repairs	Labor and materials to a.) replace the transformer that burnt out b.) the motor starter that shorted out due to the transformer burning out and this will take care of the signal to the hot water heater/boiler that is causing the trouble code				
Diagnosis: Initial Work Order	<b>Repair hot water heater, Error on screen "Service Required"</b>				
Diagnostic Fee	\$80.00				
Additional Labor Cost to Perform Repairs	\$400.00 TWI Labor \$80 x 5				
Additional Material Cost to Perform Repairs	\$ 816.06 <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>816.06</td> <td>816.06</td> </tr> </table>	Materials (See attached detail)	1	816.06	816.06
Materials (See attached detail)	1	816.06	816.06		
Total Cost of Repair	\$ 1296.06				

10981 Guilford Road  
Annapolis Junction, MD 20701-1125  
Phone: (301) 543-4900  
Fax: (301) 543-4902

**Customer Information**

TIDEWATER INC  
6625 SELNICK DR #A  
ELKRIDGE MD 21075-6220

**Billing Information**

TIDEWATER INC  
6625 SELNICK DR #A  
ELKRIDGE MD 21075-6220

**Shipping Information**

TIDEWATER INC  
6625 SELNICK DR #A  
ELKRIDGE MD 21075-6220

**Information**

Grainger Quote Number	2052752861
Quote Start Date	12/01/2022
Quote Expiration Date	12/31/2022
Creation Date	12/01/2022
Grainger EIN Number	36-1150280
PO #	
PO Create Date	
PO Release #	NONE
Customer Number	885295220
Department Number	NONE
Project/Job Number	NONE
Requisitioner Name	PATRICK BROWN
Attention	PATRICK BROWN
Caller	PATRICK BROWN
Telephone Number	3156723272
Page	1 / 2

**Freight Forwarder**

We will deliver according to the following terms and conditions:

Incoterms® 2020: FOB ORIGIN  
Freight Terms: Prepaid Parcel  
Carrier: \* See line item detail  
Payment Terms: Net 30 days after invoice date

**Special Instructions:**

Item PO-Line	Material	Description	Expected Del Date	Qty	Unit	Price	Total in USD
10	31EG97	Control Transformer,50VA,4.08 In. H Manufacturer: DAYTON Part Number: 31EG97 Carrier: Origin: US	05/31/2023	1.00	EA	145.57	145.57
20	6LDD8	NEMA Magnetic Motor Starter Manufacturer: EATON Part Number: AN19BN0A5E005 Carrier:	12/27/2022	1.00	EA	534.48	534.48

10981 Guilford Road  
Annapolis Junction, MD 20701-1125  
Phone: (301) 543-4900  
Fax: (301) 543-4902

**Information**

Grainger Quote Number 2052752861  
Creation Date 12/01/2022  
Customer Number 885295220  
Page 2 / 2

Item PO-Line	Material	Description	Expected Del Date	Qty	Unit	Price	Total in USD
Origin: DO							
						<b>Sub Total</b>	680.05
						<b>Estimated Std Parcel Ship</b>	0.00
						<b>Estimated Other Shipping</b>	0.00
						<b>Tax</b>	40.80
						<b>Total USD</b>	\$ 720.85
Thank you for the opportunity to provide this quotation.							
Please reference our Grainger quote number when you are ready to place your order.							
Any changes to the products and/or quantities identified in the quotation may result in different pricing.							
Quoted shipping charges and delivery date are subject to change. Upon acceptance of the quotation by customer, Grainger will provide actual shipping charges for the order, if applicable.							
This transaction is subject to the current contract between customer and Grainger; or if no contract exists, the Terms of Sale located at <a href="https://www.grainger.com/content/mc/policies/terms-of-sale">https://www.grainger.com/content/mc/policies/terms-of-sale</a> .							

B-1-0  
HOT WATER BOILER

**KNIGHT**  
COMMERCIAL BOILER  
**XL**

RESET

SCROLL

LOCKOUT  
OUTLET ARHL

SENSOR 1: 206°F  
SENSOR 2: 212°F

SETPOINT

SMART SYSTEM

Select

Select

