

## Additional Funding Request

|                                             |                                                                                                                                                                                                                                                          |      |       |  |                                 |    |      |       |
|---------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-------|--|---------------------------------|----|------|-------|
| <b>NY067</b>                                | <b>CSS# 90456 WO# 19750</b>                                                                                                                                                                                                                              |      |       |  |                                 |    |      |       |
| Description of Repairs                      | Labor only to install the dishwasher provided by the government.                                                                                                                                                                                         |      |       |  |                                 |    |      |       |
| Diagnosis:<br>Initial Work Order            | Repair dishwasher, water leaking form unit.                                                                                                                                                                                                              |      |       |  |                                 |    |      |       |
| Diagnostic Fee                              | NA                                                                                                                                                                                                                                                       |      |       |  |                                 |    |      |       |
| Additional Labor Cost to Perform Repairs    | 6 x \$80.00 = \$480.00                                                                                                                                                                                                                                   |      |       |  |                                 |    |      |       |
| Additional Material Cost to Perform Repairs | <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 55%;">Materials (See attached detail)</td> <td style="width: 10%;">NA</td> <td style="width: 15%;">0.00</td> <td style="width: 20%;">85.00</td> </tr> </table> |      |       |  | Materials (See attached detail) | NA | 0.00 | 85.00 |
| Materials (See attached detail)             | NA                                                                                                                                                                                                                                                       | 0.00 | 85.00 |  |                                 |    |      |       |
| Total Cost of Repair                        | \$ 480.00                                                                                                                                                                                                                                                |      |       |  |                                 |    |      |       |



ON  
10MZZ0000-00  
OFF



Asset# 10578 Sink Heater

THIS HEATER EQUIPPED WITH  
A MANUALLY RESET HIGH TEMP.  
LIMIT SWITCH (ECO). TO RESET  
1. TURN POWER OFF. 2. REMOVE  
FRONT COVER. 3. PUSH RESET  
BUTTON. 4. IF TRIPPING  
REPEATS, CALL REPAIR MAN.



HATCO CORPORATION  
MILWAUKEE, WISCONSIN

# ELECTRIC WATER HEATER

TOTAL AMPS. 1 PH.

3 PH. 33

VOLTS 208

A.C.

TOTAL KW. 12

CAP. U.S. GALS. 6

MODEL CC-12

SERIAL 11544-F08

300 LBS. TEST

150 LBS. WK. PRESS.



LISTED 568L

**HATCO CORPORATION**

MILWAUKEE, WISCONSIN

U.S. PAT. NOS.  
3357421, 189563,  
3205910,  
3240171