

Additional Funding Request

NY051	CSS# 92371 WO# 21470				
Description of Repairs	Labor and material to a.) repair roof leaks above copy room and PT rooms.				
Diagnosis: Initial Work Order	Repair roof leaks above the copier room and the gym.				
Diagnostic Fee	NA				
Additional Labor Cost to Perform Repairs	$10 \times \$100.00 = \1000.00				
Additional Material Cost to Perform Repairs	<p>\$ 325.00</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>325.00</td> <td>325.00</td> </tr> </table>	Materials (See attached detail)	1	325.00	325.00
Materials (See attached detail)	1	325.00	325.00		
Total Cost of Repair	\$ 1325.00				

HUNOLD CONTRACTING INC.

72 PENDERGAST ROAD
PHOENIX, NY 13135ackflow
Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE**3/6/23**

Quantity	Description	Amount
1	Oswego, NY. Repair roof leaks above copy room and PT rooms. Material: (Roof boots, mastic, flashing material) \$325 Labor: (10 hours @ \$100/ hr.) \$1000 Price includes all labor, equipment and material.	1325.00
		Sub total 1325.00
		Sales Tax N/A
		Total 1325.00

Signature _____ Date _____

Signature _____ Date _____