

## Additional Funding Request

NY051	CSS# 93709 WO# 22715			
Description of Repairs	Labor and material to a.) new Belimo actuator serving room 115. b.) Isolate the valve and remove the existing one c.) install the new valve. d.) pressure test and perform a system check to insure it is operating to all manufacturer specifications			
Diagnosis: Initial Work Order	Urgent - Replace VAV valve in room 115			
Diagnostic Fee	NA			
Additional Labor Cost to Perform Repairs	(8) hours x 110.00 = \$880.00			
Additional Material Cost to Perform Repairs	<table border="1"><tr><td>Materials (See attached detail)</td><td>\$1081.63</td></tr></table>		Materials (See attached detail)	\$1081.63
Materials (See attached detail)	\$1081.63			
Total Cost of Repair	\$ 1961.63			

22962 Murrock Circle  
Watertown, NY 13601  
315-788-1300 Fax 315-788-9646

SULLIVAN NH 3445  
**Attn:** PATRICK BROWN

SULLIVAN NH  
3445

Quote #:	0000003020-000
Quote Type:	Work Order
Reference:	Belimo Actuator 115
Cross Ref:	
Work Order:	n/a
Customer:	940
Terr/sale:	HSE
Current Date:	Jun 15,2023
Expiry Date:	N/A

Code	Description	Quantity	UOM	Price	Total
Hyde-Stone is pleased to quote you a new Belimo actuator serving room 115. Hyde-Stone will isolate the valve and remove existing one, then install the new valve. We will then pressure test and perform a system check to insure it is operating to all manufacturer specifications					
Please contact me with any questions or concerns. Thank you for your continued business with Hyde-Stone.					
N/A	Belimo Actuator				
N/A	Vehicle Charge				
	Material				1,081.63
TECH	Technician				
	Subtotal				880.00
Sub Total					1,961.63
Total Quotation					1,961.63