

Additional Funding Request


NY051	CSS# 94159 WO# 23329							
Description of Repairs	Labor and material to a.) unhook the electrical and plumbing b.) install a new water fountain ,reinstall the plumbing and electrical and test for proper operation							
Diagnosis: Initial Work Order	The fan inside the water fountain near the gym is sounding like it is hitting something or it is coming loose.							
Diagnostic Fee	NA							
Additional Labor Cost to Perform Repairs	5 x 85.00 = \$425.00							
Additional Material Cost to Perform Repairs	<table><tr><td>Materials (See attached detail)</td><td>NA</td><td>2058.12</td><td>2058.12</td></tr></table>				Materials (See attached detail)	NA	2058.12	2058.12
Materials (See attached detail)	NA	2058.12	2058.12					
Total Cost of Repair	\$ 2483.12							



Cart

Order Summary

Subtotal	\$1,715.10	Estimated Tax	N/A	Estimated Standard Shipping	FREE	Estimated Other Shipping	\$76.89
Estimated Total \$1,791.99							
As a Red Pass Plus member, you're getting FREE standard shipping on this order.							



ELKAY

Drinking Fountain with Bottle Filler: On-Wall, Refrigerated, 39 1/8 in Ht, Gray, Non-Filtered


Item # 60NJ95

Qty

1

Your Price

\$1,715.10 / each




Availability

Ships from supplier. Expected to arrive on or before **Fri. Sep 15**.

This item requires special shipping, additional charges may apply.


Products You Have Recently Viewed



ELKAY

Drinking Fountain with Bottle Filler: On-Wall,...

Item # 60NJ95


Your Price 

\$1,715.10 / each

Qty

1


Add to Cart



ELKAY

Drain Replacement Kit: 97969C

Item # 15W918


Your Price 

\$40.06 / each

Qty

1


Add to Cart



ELKAY

Drain Replacement Kit: 97970C

Item # 15W919


Your Price 

\$43.00 / each

Qty

1


Add to Cart



MIRACLE LED

LED Bulb: A15, Medium Screw (E26), 60W INC, 5 ...

Item # 655Y04


Your Price 

\$23.98 / pkg. of 2

Qty

1


Add to Cart



CURRENT

Fluorescent Ballast: T12/T8, 120 to 277V AC, 1_2 Bulbs...

Item # 2VIEW7

Your Price 

\$21.13 / each

Qty

1

Add to Cart

https://www.grainger.com/cart

1/1


Model
ESWA8 1G
Serial No.
040617334
Part No.
ESWA8L1Z

Volts 115 HZ 60 PH Amps 1 4.8 Watts LRA 0.0 Max Fuse 0.0 Min Circuit 0.0
Refrig. 4.35 OZ Type 134A Design Pressure - PSI HS 325.0 LS 140.0 Class U
ELKAY MANUFACTURING CO.
SAVANNA, IL, U.S.A.



Drinking Water System Components UND. LAB. INC. Classified ANS/NSF61 Section 9 1997b

ALTITUDE ADJUSTMENT



Calibr. screw
Do Not Turn

INSTALLER WARNING

If installation is located over 2000 feet above sea level - adjust cold control setting to a warmer temperature to prevent freeze-up in the water system. Make 1/8 turn counterclockwise for each 1000 feet over 2000 feet above sea level.

REV-B
90593C

