

## Additional Funding Request

NY127	CSS# 94370 WO# 23755							
Description of Repairs	Labor to a.) troubleshoot the air conditioning in the main training building							
Diagnosis: Initial Work Order	Air Conditioning in Main Training Building is not working. Attempt to reset condenser but produced negative results							
Diagnostic Fee	NA							
Additional Labor Cost to Perform Repairs	4 x 128.00 = \$512.00 \$50 Truck Charge							
Additional Material Cost to Perform Repairs	<table border="1"><tr><td>Materials (See attached detail)</td><td>NA</td><td>NA</td><td>NA</td></tr></table>				Materials (See attached detail)	NA	NA	NA
Materials (See attached detail)	NA	NA	NA					
Total Cost of Repair	\$ 562.00							



July 24, 2023

Tidewater, Inc  
881 Stanton Hill Rd.  
Nichols, NY 13812

Attn: Karlee Demain

Re: Troubleshoot Air Conditioning

Ms. Demain,

Postler & Jaeckle Service is pleased to provide a quote to troubleshoot the air conditioning in the main training building at 881 Stanton Hill Rd in Nichols, NY. This quote will be for 4 hours of labor at \$128.00/hr. for \$512.00 plus a \$50.00 truck charge for a total of \$562.00. Thank you for the opportunity to provide this quote for your facility. Please contact me with any questions.

Sincerely,

**DAVE HENDEE**

Field Sales Support

**Postler & Jaeckle Corp.**

**2000 Lake Rd., Elmira, NY 14903**

**T 607-739-8303 | C 607-215-6523**

E: [dhendee@postler.com](mailto:dhendee@postler.com)