

Date: 12/1/2023

Region: 4A

FAC ID: NY010

Asset #: NA

CSS No.: 95849

Maximo WO No.: 14511

Priority: Routine



Original Work Request:

Repair sump pump. Alarm was triggered with rising water. Water level has not gone down, but has not crested containment.

Description of Repairs Needed:

Labor to a.) diagnose sump pump alarm

Labor:	Labor Hrs	Labor Rate	Total
Technician	7	\$ 125.00	\$ 875.00
Truck Charge	1	\$ 56.00	\$ 56.00

Material List:	Quantity	Cost	Total

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 931.00	\$ -	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$931.00	\$111.72	\$55.86	\$1,098.58



GREATER NIAGARA MECHANICAL, INCORPORATED

7311 WARD ROAD ∞ NORTH TONAWANDA, NEW YORK 14120

PHONE 716.695.3600 ∞ FAX 716.695.3700

11/27/2023

Quote # 23-530

Tidewater Inc.
5835 Avenida Encinas suite 118
Carlsbad, CA 92008

RE: AMHERST USARC (NY010) SUMP PUMP DIAGNOSIS

We, at Greater Niagara Mechanical, Inc., are pleased to offer the following scope of work and pricing for your review:

Scope:

- Provide labor to diagnose sump pump alarm

Cost.....	\$	931.00
Labor/truck.....	\$	931.00
Materials.....	\$	0.00

HVAC Exclusions

- Shift or premium time
- Tax
- Anything not covered in above scope

Thank you for the opportunity to quote the above-mentioned project! Please feel free to contact us with any questions.

Sincerely,

Charles Dowd
Greater Niagara Mechanical