

Date: 2/26/2024

Region: 4C
FAC ID: WV022

CSS No.: 96325
Maximo WO No.: 14996

Asset #: NA

Priority: Routine



Original Work Request:

Repair women's toilet. Leaking at fitting on top of toilet when it's flushed.

Description of Repairs Needed:

Labor and material to a.) replace the P6000-EUR-WS-RK ZURN 1.5 GPF Urinal Rebuild Kit b.) install the P-6000-ECR-WS1 ZURN 1.6 GPF REP Kit and c.) install the 959 1-1/2 CLOSET Spud (OLD# C27-150) and test for proper operation

Labor	Labor Hrs	Labor Rate	Total
Technician	6	\$ 100.00	\$ 600.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
P6000-EUR-WS-RK ZURN 1.5 GPF Urinal Rebuild Kit	3	\$ 64.43	\$ 193.28
P-6000-ECR-WS1 ZURN 1.6 GPF REP Kit	3	\$ 52.11	\$ 156.33
959 1-1/2 CLOSET Spud (OLD# C27-150)	1	\$ 13.95	\$ 13.95

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 600.00	\$ 363.56	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$963.56	--	--	\$963.56

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 2/26/2024 CSS #: 96325
FAC ID: WV022 WO #: 14996

DESCRIPTION OF WORK			
Labor and material to a.) replace the P6000-EUR-WS-RK ZURN 1.5 GPF Urinal Rebuild Kit b.) install the P-6000-ECR-WS1 ZURN 1.6 GPF REP Kit and c.) install the 959 1-1/2 CLOSET Spud (OLD# C27-150) and test for proper operation			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	6	\$100.00	\$600.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
P6000-EUR-WS-RK ZURN 1.5 GPF Urinal Rebuild Kit	3	\$64.43	\$193.28
P-6000-ECR-WS1 ZURN 1.6 GPF REP Kit	3	\$52.11	\$156.33
959 1-1/2 CLOSET Spud (OLD# C27-150)	1	\$13.95	\$13.95
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$600.00
	MATERIAL TOTAL		\$363.56
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$963.56

Accepted By: _____

Date: _____