

Date: 3/15/2024

Region: 4C

FAC ID: WV022

CSS No.: 96542

Maximo WO No.: 15234

Asset #: NA

Priority: Routine



Original Work Request:

Repair by replacing gas valve on boiler #3. Mech room in training building.

Description of Repairs Needed:

Labor and material to a.) replace HTP Part Dungs gas valve 7350P-033 on boiler 3.

Pricing includes common motor freight charges.

Labor	Labor Hrs	Labor Rate	Total
Technician	6	\$ 100.00	\$ 600.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
HTP Part Dungs Gas Valve for EL-220, EL-299, EL-399 7350P-033	1	\$ 754.02	\$ 754.02
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$600.00	\$754.02	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,354.02	--	--	\$1,354.02

Note: G&A and Fee are not applied on top of work performed by Tidewater.

Prepared by:

Tidewater, Inc.

6625 Selknick Drive, Suite A

Elkridge, MD 21075

Prepared for:

CMI Management, Inc.

5285 Shawnee Road Suite 510

Alexandria, VA 22312-2334

Date: 3/15/2024

CSS #: 96542

FAC ID: WV022

WO #: 15234

DESCRIPTION OF WORK

Labor and material to a.) replace HTP Part Dungs gas valve 7350P-033 on boiler 3.
Pricing include common motor freight charges.

LABOR	QTY	UNIT/RATE	TOTAL
Technician	6	\$100.00	\$600.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
HTP Part Dungs Gas Valve for EL-220, EL-299, EL-399 7350P-0	1	\$754.02	\$754.02
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$600.00
	MATERIAL TOTAL		\$754.02
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$1,354.02

Accepted By: _____

Date: _____