

Date: 9/9/2024

Region: 4C

FAC ID: WV020

CSS No.: 98848

Maximo WO No.: 16635

Asset #: NA

Priority: Routine



Original Work Request:

Repair lighting controls - no outside lights are working currently.

Description of Repairs Needed:

Labor and material to a.) replace (21) Nsi Tork 2021 2000 Watt 120 Volt SPST photo cell, b.) test for proper operation.

Labor:	Labor Hrs	Labor Rate	Total
Technician	20	\$ 100.00	\$ 2,000.00
			\$ -

Material List:	Quantity	Cost	Total
Nsi Tork 2021 2000 Watt 120 Volt SPST	21	\$ 50.00	\$ 1,050.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 2,000.00	\$ 1,050.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,050.00	\$366.00	\$183.00	\$3,599.00



43 Pine Tree LN
Morgantown, WV 26508
(681) 270-0607
nselectricoffice@gmail.com

Estimate

ESTIMATE#	1050765591
DATE	09/04/2024
PO#	CSS 98848 WO16635 WV020

CUSTOMER

TIDEWATER, INC.
Julie Pape
6625 Selnick Drive
Elkridge , MD 21075
(904) 465-1981

SERVICE LOCATION

TIDEWATER, INC.
Julie Pape
Base
7605 Us Rt 19 North
Janlew , WV 26378
(904) 465-1981

DESCRIPTION

Repair parking lot lighting.

Estimate

Description	Qty	Rate	Total
Labor Hours	20.00	100.00	2,000.00
Nsi Tork 2021 2000 Watt 120 Volt SPST	21.00	50.00	1,050.00
Sales		6.000%	0.00

CUSTOMER MESSAGE

Estimate Total: \$3,050.00

PRE-WORK SIGNATURE

Signed By: