

Date: 9/24/2024

Region: 4A

CSS No.: 99021

FAC ID: NY070

Maximo WO No.: 16857

Asset #: NA

Priority: Urgent



Original Work Request:

Repair air compressor. The air compressor located in the OMS building is leaking oil and is vibrating when it is in operation. If the air compressor is not repaired, then the full-time mechanics cannot perform their work.

Description of Repairs Needed:

Labor to perform assessment on air compressor leaking oil that is located in the OMS building.
Ingersoll-Rand T30
Model No. 2475
Serial No. 00036168
Ingersoll-Rand Air Compressors Serial No. 0102270110

Labor:	Labor Hrs	Labor Rate	Total
Technician	3	\$ 152.50	\$ 457.50
Vehicle Charge	1	\$ 99.00	\$ 99.00

Material List:	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 556.50	\$ -	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$ 556.50	\$ 66.78	\$ 33.39	\$ 656.67

From: [Nick Mauro](#)
To: [Julie Page](#)
Subject: [EXTERNAL]Re: New Urgent Request NY070 CSS 99021 WO 16857 Repair Air Compressor - Estimate for Assessment
Date: Tuesday, September 24, 2024 8:57:40 AM

CAUTION: External email, DO NOT click on any links/attachments unless you recognize the sender and know the content is safe

Julie,

Sorry I have been out of the office sick. It would be \$152.50/hour (portal to portal) plus whatever time is spent on site. I would estimate around 3 hours total of labor. Then we charge a \$99.00 vehicle charge (one time charge) and that would be it. Obviously parts, oil and anything else needed would be charged but just to get an idea of coming out and diagnosing the issue, this would be accurate.

Any questions let me know. I should be back in the office tomorrow.

Thank you,	\$152.50 x 3 = \$457.50
	\$99.00
Nick	\$556.50

Nicholas Mauro
R.W. Lindsay
581 Rock Beach Rd.
Rochester, NY 14617
O - 585-544-7310
