

Additional Funding Request

VA050	CSS TBD WO# 12748 Asset# NA				
Description of Repairs	Fabricate/Impression Key for Vault/Trouble shoot Alarm Activity				
Diagnosis: Initial Work Order	Vault Safety key release is missing -Need proposal to replace key or release lock -This is for IF someone were trapped in Vault -this key would open the vault from the inside. Sending to TW to get a proposal from Advanced Security for recommended repairs				
Diagnostic Fee	\$ 250				
Additional Labor Cost to Perform Repairs	\$ 1,200 Labor \$120/hr x 10				
Additional Cost	\$ 0 <table border="1" style="width: 100%;"><tr><td style="width: 25%;"></td><td style="width: 25%;"></td><td style="width: 25%;"></td><td style="width: 25%;"></td></tr></table>				
Total Cost of Repair	\$ 1,450.00				

ADVANCED SECURITY SAFE & LOCK
6318 REISTERSTOWN RD
BALTIMORE, MD 21215

Tel: (410) 764-2001
Tel: (877) 267-6562
Fax: (410) 561-6031
Email: Billing2@ampmlock.com
www.AMPMLOCK.com

Estimate

Date	Estimate #
9/1/2020	30572

Customer Information
Tidewater PM 3761 Attucks Drive Powell, OH 43065

Item	Description	Qty	Cost	Total
SERVICE CALL	Service Call	1	250.00	250.00
LABOR	Fabricate/Impression Key Release for Interior of Vault	3	120.00	360.00
LABOR	Troubleshoot Alarm Activity - Panel	7	120.00	840.00
	Service Location: VA050			
	WO# ? CSS# ?			

WE LOOK FORWARD TO ASSISTING YOU!

Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty.

SIGNATURE: _____

DATE: _____

Terms: 50% deposit and 50% due upon completion

Subtotal	\$1,450.00
Sales Tax (0.0%)	\$0.00
Total	\$1,450.00