

Additional Funding Request

INVOICE

VA048	CSS# TBD WO# 13821 Asset# NA				
Description of Repairs	Troubleshoot over the phone with personnel on site to reset CAC system.				
Diagnosis: Initial Work Order	power outage over the weekend . The CAC system and main gate are not working				
Diagnostic Fee	\$ 0				
Additional Labor Cost to Perform Repairs	<p>\$ 690</p> <p>LoCurrent Emergency Labor \$450/hr x 1</p> <p>TWI Emergency Labor \$120/hr x 2</p>				
Additional Material Cost to Perform Repairs	<p>\$ 0</p> <table border="1"> <tr> <td>N/A</td> <td>1</td> <td>0</td> <td>0</td> </tr> </table>	N/A	1	0	0
N/A	1	0	0		
Total Cost of Repair	\$ 690.00				

LoCurrent Systems, LLC

3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



INVOICE

BILL TO

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

INVOICE # 1861
DATE 02/25/2021
DUE DATE 03/27/2021
TERMS Net 30

P.O. NUMBER

Monteith VA048 Phone Diagnosis

ACTIVITY	QTY	RATE	AMOUNT
Installation (No correlating Estimate- Emergency Service) WO#13821 Monteith Facility USARC VA048 Troubleshoot over the phone with personnel on site to reset CAC System.	1	450.00	450.00

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300. **BALANCE DUE**

\$450.00