

Region: 5

Location: MD019

CSS #: NA

Maximo Work Order No.: 12765

Asset #: NA

Date Issued: 8/28/20

Original Description: Proposal to upgrade to LED bulbs for wall pack lights on main building , pump house , OMS- Main gate sign

Repairs Needed:

Labor and materials to repair/convert all exterior wall pack lights to LED on all buildings and Sign at MD019.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials (See attached Detail)	--	--	\$6,174.00	--	\$6,174.00
--	NA	TW Diagnostic and Repair Labor	26	\$80.00	--	--	\$2,080.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
26	\$2,080.00	\$6,174.00	--	\$8,254.00	100%	\$8,254.00



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	MD019
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Exterior
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to repair/convert all exterior wall pack lights to LED on all buildings at MD019.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			24	\$1,920.00
LED Replacment Bulb 429U52	25	\$246.96		\$6,174.00
				\$0.00
				\$0.00
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$6,174.00	Labor \$2,080.00
TOTAL			\$8,254.00	

All Products ▾

Enter keyword, item, model or part #



Bulk Order ▾

My Account ▾



Product Categories / Lighting / Light Bulbs & Lamps / HID & LED HID-Replacement Light Bulbs & Lamps / LED Replacement Bulb, ED37, Mogul Screw (EX39...

Email

Print



Roll over image to zoom.

GE CURRENT

LED Replacement Bulb, ED37, Mogul Screw (EX39), 5,000 K, 23,500 lm, 150W, 120-277

Item # [429U52](#)

Mfr. Model # LED150ED28/750

UNSPSC # 39112102

Catalog Page # [508](#)

These HID and LED HID-replacement light bulbs have an extended mogul screw base, also called an EX39 base. The EX39 base has a longer center terminal than an E39 base and can be screwed into both E39 sockets, which are typically found on enclosed fixtures, or protected EX [View More ▾](#)

Country of Origin China. Country of Origin is subject to change.

☐ Compare this product

Web Price ⓘ

\$196.00 / each

Qty

1

Add to Cart☒ Shipping☐ PickupExpected to arrive **Mon. Sep 28**.Ship to **43065** | [Change](#)[Ship Availability Terms](#)Shipping Weight **2.45 lbs**[Add to List](#)







