

Date: 2/1/2024

Region: 4C
FAC ID: WV029

CSS No.: 96299
Maximo WO No.: 15006

Asset #: NA

Priority: Urgent



Original Work Request:

Repair video feed for security - lost one of the feeds over the weekend to see the vehicles at the gate.

Description of Repairs Needed:

Labor and material to replace existing nonfunctional pole camera looking at entry pedestal.

Labor:	Labor Hrs	Labor Rate	Total
Technician (2 Men)	8	\$ 95.00	\$ 1,520.00
			\$ -

Material List:	Quantity	Cost	Total
Color, Day/Night Dome Camera w/ Gooseneck and Mounting Cup	1	\$ 475.00	\$ 475.00

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,520.00	\$ 475.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,995.00	\$239.40	\$119.70	\$2,354.10

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

Ms. Jennifer Bailie
 USAR (GTS)

ESTIMATE # 2408**DATE** 01/02/2024**P.O. NUMBER**

Morgantown, WV Replace Camera

	ACTIVITY	QTY	AMOUNT
01/02/2024	Services Morgantown, WV USARC Replace Existing Nonfunctional Camera looking at Entry Pedestal	1	1,995.00

Dear Ms. Bailie,

As per your request, LoCurrent Systems is pleased to provide a quotation to Replace Existing Nonfunctional Pole Camera looking at Entry Pedestal at the Morgantown, WV USARC.

Cost Breakdown:

Color, Day/Night Dome Camera w/ Gooseneck and Mounting	
Cup.....	\$475.00
(2) Men 8 Hours @ \$95.....	\$1,520.00

Grand	
Total.....	\$1,995.00

The Total Cost for the above mentioned work is \$1,995.00.

If acceptable, please do not hesitate to contact us so we may schedule for work to be completed.

Thank you for thinking of LoCurrent Systems.

Sincerely,

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		
	TOTAL	\$1,995.00

Accepted By

Accepted Date