

Date: 6/5/2024

Region: 4C

CSS No.: 97909

FAC ID: WV009

Maximo WO No.: 15620

Asset #: NA

Priority: Routine



Original Work Request:

Repair 12 ballasts in mechanical room and repair lightbulbs at the top of the stairs.

Description of Repairs Needed:

Labor and material to a.) replace (8) GE LED 32W T8/12 4FT bulbs, b.) test for proper operation.

Labor	Labor Hrs	Labor Rate	Total
Technician	6	\$ 100.00	\$ 600.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
GE LED 32W T8/12 4FT	8	\$ 13.49	\$ 107.90
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$600.00	\$107.90	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$707.90	--	--	\$707.90

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selkirk Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 6/5/2024 CSS #: 97909
FAC ID: WV009 WO #: 15620

DESCRIPTION OF WORK			
Labor and material to a.) replace (8) GE LED 32W T8/12 4FT bulbs, b.) test for proper operation.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	6	\$100.00	\$600.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
GE LED 32W T8/12 4FT	8	\$13.49	\$107.90
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$600.00
	MATERIAL TOTAL		\$107.90
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$707.90

Accepted By: _____

Date: _____