

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA012 Date of Visit: 2-JUN-2025

Contractor Personnel on Site:

1. Aaron Skeens 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO19506 FEMS3190226 Heat Pump in AMSA shop not operating

Service Calls – Service Call Number and Description


1. CSS# Heat pump has been repaired. Failed due to blown fuse.
2. CSS# 2- 30 AMP bus fuses replaced in disconnect.
3. CSS# Added 1 oz of R-410A correcting refrigerant levels.

-AS

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Aaron Skeens Date: 2-JUN-2025


Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.

This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Joseph Lael Date: 2-JUN-2025

Signed: 

E-Mail: Joseph.w.lael.civ@army.m

