

Tina Lee

From: Richard Hicks
Sent: Wednesday, June 8, 2022 3:34 PM
To: Augustin, Kenneth P CIV USARMY 99 RD (USA); Gavin, Jason D CTR USARMY 99 RSC (USA); Adam Colopy; Mary Lowery; Shara Fortier; Tina Lee
Cc: Devlin, Thomas J CIV USARMY CENAP (US)
Subject: DE007 -01 Oil Water Separator
Attachments: 2022 Cleaning and Inspection Report.pdf

Ken , Tom , Team ,
Per our conversation , AEG Environmental serviced the wrong OWS tank at DE007 . The tank at Building #1 OMS shop was pumped out and inspected , see attached report . This will replace the OWS tank service at DE007-04 new site since the building is still un-occupied .

Tina ,please upload report to WO# 16748 . and PDF this email also

DE007-04	16748	OY4-238	PMSA-OY4-238		1-pc OWS 550-Gal Exterior----NEED INSPECTED BY AEG
----------	-------	---------	--------------	--	--

Note : CSS Ticket needed – DE007 -01 Several of the bolts holding the covers on the OWS had to be broken to remove the lid and should be replaced

Thanks,
Rick

Rick Hicks
Project Manager Region 5
CMI Management Inc.
5285 Shawnee Road Suite #510
Alexandria,VA 22312
703-738-5301
Richard.Hicks@cmimgmt.com