

Date: 11/20/2024

Region: 4C
FAC ID: WV010

FEMS No.: 2897054
Maximo WO No.: 17052

Asset #: NA

Priority: Urgent



Original Work Request:

Repair Heat in Motor pool- Tube heaters are not working.

Description of Repairs Needed:

Labor and material to a.) replace (1) TMJ430 capacitor, b.) supply & install (1) HER-90604500 3/4HP Motor CO-RAY-VAC, c.) test for proper operation. Clean area and properly dispose of all spent materials.

Labor	Labor Hrs	Labor Rate	Total
Technician	10	\$ 100.00	\$ 1,000.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
TMJ430 Capacitor Start PM 430-516MFD 110-125V	1	\$ 10.34	\$ 10.34
Inducer Motor HER-90604500 3/4HP	1	\$ 1,319.40	\$ 1,319.40
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$1,000.00	\$1,329.74	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,329.74	--	--	\$2,329.74

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 11/20/2024 FEMS #: 2897054
FAC ID: WV010 WO #: 17052

DESCRIPTION OF WORK

Labor and material to a.) replace (1) TMJ430 capacitor, b.) supply & install (1) HER-90604500 3/4HP Motor CO-RAY-VAC, c.) test for proper operation. Clean area and properly dispose of all spent materials.

LABOR	QTY	UNIT/RATE	TOTAL
Technician	10	\$100.00	\$1,000.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
TMJ430 Capacitor Start PM 430-516MFD 110-125V	1	\$10.34	\$10.34
Inducer Motor HER-90604500 3/4HP	1	\$1,319.40	\$1,319.40
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:		LABOR TOTAL	\$1,000.00
		MATERIAL TOTAL	\$1,329.74
		EQUIPMENT TOTAL	\$0.00
TOTAL COST:			\$2,329.74

Accepted By: _____

Date: _____