

Date: 3/24/2025



Region: 4C

CSS No.: 2935336

FAC ID: WV022

Maximo WO No.: 17345

Asset #: NA

Priority: Routine

Original Work Request:

Repair faulty 3-way light switch in Drill Hall.

Description of Repairs Needed:

Labor and material to a.) replace (2) 3-way light switches CSB3-201, b.) test for proper operation, c.) clean up and properly dispose of all spent materials.

Labor:	Labor Hrs	Labor Rate	Total
Technician	6	\$ 90.00	\$ 540.00
			\$ -

Material List:	Quantity	Cost	Total
Leviton CSB3-201 20 amp 3-way switch	2	\$ 12.00	\$ 24.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 540.00	\$ 24.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$564.00	\$67.68	\$33.84	\$665.52



DBA TC3 Services
142 Terrace Manor
Fairmont, WV 26554

Estimate

Date	Estimate #
3/24/2025	1079

Name / Address
Tidewater Inc Julie Pape 6625 Selnick Drive, Ste A Elkridge, MD 21075

Description	Hours	Rate	Total
Preston County CSS: 2935336 WO: 17345 Light switches not working properly in drill hall. Replace (2) two 3-way switches. Materials: Leviton CSB3-201 20 AMP 3-way switch Labor:	2 6	12.00 90.00	24.00 540.00
Thank you for doing business with Tri-City Electric!		Total	\$564.00
Approval Signature:			
tcmelissa@gmail.com	Phone: 304-363-2843		