

Date: 5/8/2025

Region: 4A

FAC ID: NY070

Asset #: NA

FEMS No.: 3156260

Maximo WO No.: 18793

Priority: Routine



Original Work Request:

Replace 3 stairwell lights fixtures, 2 are fluorescent with bad ballast. The other is LED. All are emergency fixtures. Locations are: Stairwells 169, 135 and 125.

Description of Repairs Needed:

Labor and material to a) provide and replace (3) TSLED4-36N/D10/E2 stairwell light fixtures with LED battery backup, stairwells 169, 135, and 125, b) test for proper operation, c) clean-up and properly dispose of all spent materials at job site.

Labor:	Labor Hrs	Labor Rate	Total
Technician	8	\$ 100.00	\$ 800.00
			\$ -

Material List:	Quantity	Cost	Total
TSLED4-36N/D10/E2 Light fixture	3	\$ 349.00	\$ 1,047.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 800.00	\$ 1,047.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,847.00	\$221.64	\$110.82	\$2,179.46

HUNOLD CONTRACTING INC.

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape

6625 Selmick Dr., Suite A

Elkridge, MD 21075

ESTIMATE**5/7/25**

Quantity	Description	Amount
1	FEMS 3516260, WO 185793, NY070 Webster, NY Replace stairwell light fixtures with LED battery backup. Stairwells 169,135 and 125. Replace with RAB model # TSLED4-36N/D10/E2. (\$349/ ea.) Material: (\$1047) Labor: (8 hours @\$100/ hr.) =\$800	1847.00
Sub total		1847.00
Sales Tax		N/A
Total		1847.00

Signature_____ Date_____

Signature_____ Date_____