

Date: 7/22/2025

Region: 4C

FAC ID: WV046

Asset #: NA

FEMS No.: 3259593

Maximo WO No.: 19780

Priority: Emergency



Original Work Request:

Repair fire alarm panel as the building was struck by lightning and is not functioning.

Description of Repairs Needed:

Troubleshoot ground fault - PMI needs replaced. Labor and material to a.) supply and replace (1) Periphery Board 504 for Siemens 924 Fire Panel, b.) supply and install (1) surge protection, c.) program panel and test system.

Labor:	Labor Hrs	Labor Rate	Total
Technicians	13	\$ 120.00	\$ 1,560.00
Labor for assessment (\$480 - \$198.00 = \$282.00)	1	\$ 282.00	\$ 282.00

Material List:	Quantity	Cost	Total
Periphery Board 504 for Siemens 924 Fire Panel	1	\$ 1,795.00	\$ 1,795.00
Surge protection	1	\$ 75.00	\$ 75.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -


PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,842.00	\$ 1,870.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,712.00	\$445.44	\$222.72	\$4,380.16



## SERVICE QUOTE

QUOTE NO.	QUOTE DATE	EXPIRATION
<b>B494</b>	7/22/2025	8/20/2025

**To:** Tidewater, Inc.  
 6625 Selnick Drive, Suite A  
 SUBMIT ON PORTAL!!!!!!!!!!!!  
 Elkridge, MD 21075  
 (724) 678-6067  
 julie.pape@tideh2o.net  
 TIDEWATE

**Site:** USARC - Parkersburg  
 4603 Camden Avenue  
 EMAIL INVOICES!  
 Parkersburg, WV 26101  
 (740) 629-0749  
 USARCPB

**Brewer & Company is pleased to provide a quote for the following item(s):**

QTY	DESCRIPTION	UNIT PRICE	EXTENDED TOTAL
1	Periphery Board 504 for Siemens 924 Fire Panel	1,795.00	1,795.00
1	Surge Protector	75.00	75.00
4	Initial Site visit and diagnosis of fire panel	120.00	480.00
13	Return trip, install board, program panel and full system test	120.00	1,560.00

<b>TOTAL</b>	<b>\$ 3,910.00</b>
--------------	--------------------

- All sprinkler work shall be in accordance with NFPA 13 and WV State Fire Code. No shop drawings will be provided/required unless noted otherwise above.
- All alarm work shall be in accordance with NFPA 70, 72, and WV State Fire Code. No shop drawings will be provided/required unless noted otherwise above.
- All sprinkler inspections shall be in accordance with NFPA 25 and WV State Fire Code. All alarm inspections shall be in accordance with NFPA 72 and WV State Fire Code. All extinguisher inspections shall be in accordance with NFPA 10 and WV State Fire Code.
- Excluded work consists of shop drawings, hydraulic calculations, fire extinguishers, and fire watches unless noted otherwise above.
- All electrical work excluded unless noted otherwise above.
- All work quoted to be performed during normal working hours unless noted otherwise above.
- All applicable taxes are not included unless noted otherwise.
- All quotes are subject to credit approval and Brewer credit limits. A deposit may be required.
- Customer agrees to pay all costs of collection up to and including court costs, collection fees, attorney's fees of not less than 33% of unpaid principal and interest. Outstanding balances are subject to 2% per month interest charges.
- Size, brand, model and style of quoted equipment may be required after submission for approval to authority having jurisdiction (AHJ). Additional equipment which is not included in this quote is sometimes required by the AHJ, unforeseen circumstances or changes in scope or occupancy by the owner or AHJ. Additional required labor and material will be billed on a time and material basis.
- Delays or repeat trips as caused by the customer, customer's representative or site conditions may result in additional labor charges to be billed on a time and material basis.

# BREWER

& COMPANY OF WV, INC.



- The owner should be aware that condensation can build up in a short time on a dry pipe system even quickly as a week; the low drains need to be drained on a regular schedule to correspond with this build-up. Also, valve houses and all parts of premises should be properly heated to prevent freezing.
- The Company does not guarantee or warrant the existing or ongoing condition or operation of any system or of the same and the liability, if any, of the Company to the subscriber for any report, act or omission hereunder shall in no event exceed ONE HUNDRED DOLLARS (\$100.00). Our warranty is limited to the parts replaced or repaired only.
- **Indemnification.** Customer agrees to indemnify and hold harmless Contractor, its shareholders, directors and officers, successors and assigns from any and all losses, liabilities, claims or demands whatever caused in whole or part by the Customer's negligent acts or omissions, including, but not limited to, any loss arising from breach of contract or improper performance by Customer, for injuries to any person (including death) or damages to property growing out of the performance of this work which results from the acts or omissions of the Customer or other parties.
- **Please forward a copy of your WV Sales Tax Certificate or Direct Pay/Tax Exempt Form.**

If you have any questions, please contact me.

Thank you,  
Casey Harbour  
304-807-3566 cell

Approved by: \_\_\_\_\_

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

PO: \_\_\_\_\_