

Additional Funding Request

| Site: WV022 | WO#5909 | CSS # 15504 | Asset# NA |
|--|--|--------------------|------------------|
| Description of Repairs | Kitchen Ceiling is Leaking | | |
| Diagnosis: Initial Work Order CSS# 15504 | Repair Leaks in Ceiling | | |
| Explanation of Additional Costs for Repairs | Repair Leaks in Ceiling | | |
| Additional Labor Cost to Perform Repairs | 3 Roofers @ \$40.00x 12.5 Hours- \$1,500 Incurred 11.25 Hours @ 40/hr- \$450.00 | | |
| Additional Material Cost to Perform Repairs | Proguard Liquid Rubber- \$360.00 2 Bundles Shingles- \$80.00 | | |
| Total Cost of Repair | \$2,390.00 | | |
| | | | |
| | | | |

