

Additional Funding Request

Site: WV010	WO#6863	CSS # 16688	Asset# NA
Description of Repairs	Repair Boiler #1 in Training Room		
Diagnosis: Initial Work Order CSS# 16688	Repair Ignitor Switch		
Explanation of Additional Costs for Repairs	Repair Ignitor Switch		
Additional Labor Cost to Perform Repairs	4 x \$115- \$460.00		
Additional Material Cost to Perform Repairs	Ignitor- \$89.10 Shipping- \$26.00 Trip Charge- \$35.00 Supply Charge- \$10.00		
Total Cost of Repair	\$620.10		

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV010

Date of Visit: 12/18/18

Contractor Personnel on Site:

1. Steve Tregear

2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 155240

Service Calls – Service Call Number and Description

1. CSS# 16688
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Steve Tregear Date: 12/18/18

Signed: ST

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: JOHN THOMAS / SC1T Date: 12-18-18

Signed: JW

E-Mail: john.w.thomas.11.mil@mail.mil

