



Repairs were found while performing original repairs.

This proposal is to remove and replace the Taco pump and flanges.

CMI Cost Estimate								
Funding Request								
PA050 Indiana								
Remove & replace defective Taco Pump								
CSS #14159 - CMI # 7182								
Prepared By: J. Bayne								
1.07.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	5						\$ 490.00
1.2 Pressure Relief valve					\$ -	\$ -	\$ -	\$ 810.45
1.3 Consumables								\$50.00
1.4 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 1,374.45
2. Initial Service Call Investigation								
Grand Total								\$ 1,374.45