



Routine - AAFES - warehouse air curtain -does not stop operating when door is close

Labor and material to replace one (1) limit switch.

CMI Cost Estimate								
Funding Request								
PA166 Coraopolis								
warehouse air curtain								
CSS #16295 - CMI # 8085								
Prepared By: J. Bayne								
3.04.19								
P3 Routine								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	6						\$ 588.00
1.2 Limit Switch					\$ -	\$ -	\$ -	\$ 185.58
20% mark up								\$ 37.12
Sub Total Repair Cost								\$ 810.70
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	2						\$ 196.00
Grand Total								\$ 1,006.70