

FILTER REPLACEMENT

DATE: 8-AUG-2025

FINISH TIME: 10AM

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Technician

Additional Notes: Tube heaters have been cleaned and operating well. No issues.
Asset #9028, #9029 and #9030 are all part of Asset #9055
-AS

Page 1 of 1