

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY051 BLDG1 Date of Visit: 1/6/22

Contractor Personnel on Site:

- | | |
|-------------------------|----------|
| 1. <u>Patrick Brown</u> | 3. _____ |
| 2. _____ | 4. _____ |

Work Performed:


Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO#'S , 15731 , 15732 , 15753 , 15754 , 15850 , 15862 , 15872 , 15755 ,
2. 15863
3. ASSET#'S , 10066 , 10069-10071 , 10078 , 190917- , 294 , 299 , 277 ,
4. 285 , 302
5. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Patrick Brown Date: 1/6/21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SFC ERIC ABBOTT Date: 1/6/21

Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

INTERIOR LIGHTING

ACTIVITY AND BLDG #: NY051 BLDG1 &BLDG2

MECHANIC
SIGNATURE: 

DATE: 1/6/22

LOCATION/RM #: BLDG1 & 2

WO# 15862,

ASSET # 190917-,

START TIME: 9:30am

FINISH TIME: 10:30am

15863

277,302

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Visually check all accessible areas for burned out bulbs and/or flickering lights. Check with the facility manager to see if they know of any outages.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	no flickering lights
2	Replace bulbs where applicable. Note quantity of bulbs replaced. If lift is required, schedule accordingly.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	no bulbs needed to be replaced
3	Test light fixture. If light does not work, replace starters and/or ballasts as necessary.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	no starters or ballast replaced
4	Note and report any needed electrical repairs.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	no needed electrical repairs
5	Properly dispose of any non-working bulbs and ballasts.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
6	Clean up area and remove any trash.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: